

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897**Our File No:** CC3/AIS23005238/RVP3E2**Date:** 20/06/2023REFERENCE

Insured/Claimant: MERCEDES-BENZ FLEET MANAGEMENT SINGAPRE PTE LTD

Policy No: SP2003907937

Date of Loss: 20/01/2023

Nature of Claim: OD Claim No: 202332007812

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNJ104R**

Make &amp; Model: MERCEDES-BENZ S450L, 3.0 DAP RSAB (A)

Engine No: 25693030553090

Reg. Date: 16/12/2022 (Man. Year: 2022)

Chassis No: W1K2231602A165978

Colour: Blue

Odometer: 2999 km

Engine Capacity: 2999 cc

Market Value/New Car Price: S\$532,000.00

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/45 R19 Rear Tyre Size: 255/45 R19

Front Left Side: Pirelli 7 mm Rear Left Side: Pirelli 7 mm

Front Right Side: Pirelli 7 mm Rear Right Side: Pirelli 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,395.87	2,636.08	1,759.79	40.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,240.00	2,360.00	880.00	27.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,635.87</b>	<b>4,996.08</b>	<b>2,639.79</b>	<b>34.57</b>
<b>+ GST 8.00/8.00% (S\$)</b>	<b>610.87</b>	<b>399.69</b>	<b>211.18</b>	<b>34.57</b>
<b>Nett Amount (S\$)</b>	<b>8,246.74</b>	<b>5,395.77</b>	<b>2,850.97</b>	<b>34.57</b>

INSPECTION

Date of Assignment: 23/05/2023

Date Inspected: 23/05/2023 Inspected At:

Cycle & Carriage Industries Pte Ltd (Pandan Loop)  
188 Pandan Loop  
Singapore 128378

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,166.12 NETT)

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jun 2023)
<b>Parts:</b>	143	MERCEDES-BENZ S450L 3.0 DAP RSAB (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SNJ104R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,182.24 FS	*2,182.24 FS
2	1		*LH /REAR BUMPER TRIM STRIP	Necessary	116.36 FS	*116.36 FS
3	1		*RH /REAR BUMPER TRIM STRIP	Necessary	116.36 FS	*116.36 FS
4	1		*REAR BUMPER LOWER PART	*Check	775.93 FS	*- FS
5	1		*LH /TAIL PIPE TRIM STRIP	Cracked	221.12 FS	*221.12 FS
6	1		*LH/REAR BUMPER MOUNTING RAIL	*Check	150.19 FS	*- FS
7	1		*LH /OUTER REAR LAMP COMBINATION	Not Necessary	833.67 FS	*- FS
					<b>Total Parts (\$\$)</b>	<b>4,395.87</b>
						<b>2,636.08</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH	New	1,440.00	960.00
2	RESPRAY REAR BUMPER	New	960.00	800.00
3	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	New	480.00	480.00
4	CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE	New	120.00	120.00
5	CHECK DAMPING FOR RADAR BEAM ON REAR BUMPER (AFTER QUICK TEST) (*Check)	New	240.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,240.00</b>	<b>2,360.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >