

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 7949D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEEP CUT/ TORN	835.00	702.10
1	N/S FRONT BUMPER SIDE RETAINER	NOT NECESSARY	160.00	-
1	N/S FRONT FENDER	TO REPAIR SEE LABOUR	769.00	-
1	N/S FRONT FENDER EMBLEM	NECESSARY	88.00	66.80
1	N/S FRONT FENDER LAMP	SCRATCHED	58.00	58.00
1	N/S WING MIRROR	CUT	896.00	896.00
1	N/S WING MIRROR COVER	CUT	128.00	128.00
1	N/S FRONT DOOR PROTECTOR	CUT/NECESSARY	282.00	282.00
1	N/S REAR DOOR PROTECTOR	CUT/NECESSARY	282.00	282.00
	LESS 25% DISCOUNT		-874.50	-603.72
			2,623.50	1,811.18
	SPECIAL NETT ITEMS			
1	FRONT BUMPER CLIP (SN)	NECESSARY	40.00	40.00
1	FRONT BUMPER RIVET (SN)	NOT NECESSARY	60.00	-
1	N/S FRONT FENDER INNER SHIELD CLIP (SN)	NOT NECESSARY	40.00	-
			140.00	40.00
	<u>LABOUR</u>			
	TO RUST PROOF PANELS.	NOT NECESSARY	150.00	-
	TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, REPLACEMENT OF PARTS AND ALIGN THE SAME. INCLUSIVE OF THE REPAIR OF N/S FRONT FENDER.		700.00	400.00
	TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA.		1,200.00	1,000.00
			2,050.00	1,400.00
	GRAND TOTAL		4,813.50	3,251.18

Report Ref No. CS/LIP23005239/Uvp3m4



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	2,600.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/LIP23005239/Uvp3m4

MARKET VALUE: \$65,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$23,812.00=NETT VALUE: \$41,188.00

CHUA KANG SENG

**Licensed Appraiser**