



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMS 3950J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BONNET	DENTED	1,889.70	1,889.70
1	HEADLAMP LH	CRACKED	2,789.60	2,789.60
1	FRT BUMPER	TO REPAIR SEE LABOUR	1,329.30	-
1	FRT BUMPER RETAINER	NOT NECESSARY	102.30	-
1	FRT PARKING SENSORS	NOT NECESSARY	284.90	-
	LESS 10% DISCOUNT		-639.58	-467.93
			5,756.22	4,211.37
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING.		80.00	30.00
	TO SPRAY PAINTING DAMAGED PORTION, INCLUDING SUPPLY OF PAINT MATERIALS SUCH AS MASKING TAPE, SAND PAPERS, PRIMER, POLISHING COMPOUND AND CHEMICAL ETC.		900.00	500.00
	TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING / WELDING WORKS. INCLUSIVE OF THE REPAIR OF FRT BUMPER.		750.00	400.00
	PROGRAMME AND SETTING.	NOT NECESSARY	350.00	-
			2,080.00	930.00
<b>GRAND TOTAL</b>			<b>7,836.22</b>	<b>5,141.37</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,100.00</b>
---	--	--	-----------------

Report Ref No. CS/LIP23005243/Avp3e2

MARKET VALUE: \$62,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$29,877.00=NETT VALUE: \$32,123.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.