



Main Office : No. 22, Jalan Klang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/116, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading

Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER:
UNKNOWN

Allianz Insurance Singapore Pte. Ltd. (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	16/05/2023
Vehicle Reg. No.:	SLH1234B	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA HARRIER, 2.0 ELEGANCE (A)	Vehicle Reg. Date:	07/10/2016
Vehicle Colour:	BLACK		
Engine No:	3ZRB844649	Chassis No:	ZSU600085206
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Present Location:	MOVA AUTOMOTIVE PTE LTD (FAN YOONG)		

COST OF CLAIMS

	Amount
Parts	15,392.80
Miscellaneous Items	0.00
Labour	3,900.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	19,292.80
+ GST 8.00% (\$\$)	1,543.42
Nett Amount (\$\$)	20,836.22

This claim is handled by: ONG

Generated using Merimen e-Claims internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 May 2023)
 Parts: M1-SUV TOYOTA HARRIER 2.0 Elegance (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SLH1234B)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR TAILGATE <i>hu</i>	0.00	0.00	*830.00 F
2	1		*REAR TAILGATE GARNISH COVER <i>cm</i>	0.00	0.00	*580.00 F
3	1		*REAR TAILGATE GARNISH COVER MOULDING <i>cm</i>	0.00	0.00	*130.00 F
4	1		*REAR TAILGATE GARNISH COVER LOGO EMBLEM <i>hu</i>	0.00	0.00	*52.00 F
5	1		*REAR TAILGATE HARRIER EMBLEM <i>hu</i>	0.00	0.00	*62.00 F
6	1		*REAR TAILGATE INNER LOCK	0.00	0.00	*260.00 F
7	1		*REAR TAILGATE BACK UP LAMP LH <i>cm</i>	0.00	0.00	*230.00 F
8	1		*REAR TAILGATE HINGE LH ?	0.00	0.00	*85.00 F
9	1		*REAR TAILGATE HINGE RH ?	0.00	0.00	*85.00 F
10	1		*REAR TAILGATE RUBBER <i>hu</i>	0.00	0.00	*220.00 F
11	1		*REAR TAILGATE SPOILER ?	0.00	0.00	*1,830.00 F
12	1		*REAR TAILGATE INNER COVERING TOP <i>de</i>	0.00	0.00	*340.00 F
13	1		*REAR TAILGATE INNER TRIM ?	0.00	0.00	*320.00 F
14	1		*REAR TAILGATE SIDE INNER COVERING LH <i>de</i>	0.00	0.00	*135.00 F
15	1		*REAR TAILGATE SIDE INNER COVERING RH <i>de</i>	0.00	0.00	*135.00 F
16	1		*REAR WIPER MOTOR ASSY <i>X</i>	0.00	0.00	*420.00 F
17	1		*REAR WINDSCREEN GLASS <i>hu</i>	0.00	0.00	*520.00 F
18	1		*REAR WINDSCREEN MOULDING <i>hu</i>	0.00	0.00	*85.00 F
19	1		*REAR WINDSCREEN SEAL <i>hu</i>	0.00	0.00	*56.00 F
20	1		*REAR WINDSCREEN SEALANT <i>hu</i>	0	0.00	*40.00 FS
21	1		*REAR VIDEO CAMERA <i>MIS</i>	0	0.00	*400.00 FS
22	1		*REAR BUMPER <i>de</i>	0.00	0.00	*780.00 F
23	1		*REAR BUMPER REVERSE SENSOR <i>hu</i>	0	0.00	*200.00 FS
24	1		*REAR BUMPER SIDE RETAINER BRACKET LH <i>hu</i>	0.00	0.00	*68.00 F
25	1		*REAR BUMPER UPPER HOLDER BRACKET LH <i>hu</i>	0.00	0.00	*64.00 F
26	1		*REAR BUMPER SIDE RETAINER BRACKET RH <i>X</i>	0.00	0.00	*68.00 F
27	1		*REAR BUMPER LOWER LIP <i>de</i>	0.00	0.00	*290.00 F
28	1		*REAR BUMPER INNER SPONGE ?	0.00	0.00	*73.00 F
29	1		*REAR BUMPER CLIPS <i>hu</i>	0	0.00	*50.00 FS
30	1		*REAR TAILLAMP LAMP RH	0.00	0.00	*290.00 F
31	1		*REAR TAILLAMP LAMP LH <i>hu</i>	0.00	0.00	*290.00 F
32	1		*REAR TAILLAMP PANEL LH <i>hu</i>	0.00	0.00	*280.00 F
33	1		*REAR END PANEL <i>hu</i>	0.00	0.00	*390.00 F
34	1		*REAR END PANEL TOP COVERING ?	0.00	0.00	*240.00 F
35	1		*REAR END PANEL INNER COVERING ?	0.00	0.00	*130.00 F
36	1		*REAR SPARE TYRE PANEL UPPER BOARD ?	0.00	0.00	*420.00 F
37	1		*REAR TOOL KIT BOX ASSY ?	0.00	0.00	*530.00 F
38	1		*REAR SPARE TYRE PANEL UPPER SIDE BOARD LH ?	0.00	0.00	*280.00 F
39	1		*REAR SPARE TYRE PANEL UPPER SIDE BOARD RH ?	0.00	0.00	*260.00 F
40	1		*REAR LUGGAGE SIDE TRIM LH ?	0.00	0.00	*440.00 F
41	1		*REAR LUGGAGE SIDE TRIM RH ?	0.00	0.00	*440.00 F
42	1		*REAR QUATER PANEL LH <i>hu</i>	0.00	0.00	*790.00 F
43	1		*REAR QUATER PANEL LOWER SILL PANEL LH <i>hu</i>	0.00	0.00	*330.00 F
44	1		*REAR QUATER PANEL AIR VENTILATOR LH <i>de</i>	0.00	0.00	*90.00 F
45	1		*REAR SIDE GLASS SEALANT LH <i>hu</i>	0	0.00	*40.00 FS
46	1		*FRONT BUMPER <i>requir</i>	0.00	0.00	*330.00 F
47	1		*FRONT BUMPER CLIPS <i>X</i>	0	0.00	*50.00 FS
48	1		*REAR END PANEL JOINT SEALANT <i>hu</i>	0	0.00	*40.00 FS
49	1		*REAR SPARE TYRE PANEL - REPAIR	0.00	0.00	-
50	1		*REAR DOOR LH - REPAIR	0.00	0.00	-

F=Franchise part. S=SpcNett.

Sub Total (\$\$) 14,068.00
 + Margin on L,N Items 10.00% (\$\$) 1,324.80
 Total Parts (\$\$) 15,392.80

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

here are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE & REPLACE, REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT, REAR WINDSCREEN MOULDING & ETC	New	120.00
2	TO REMOVE & REPLACE, REFIT REAR TAILGATE REVERSE CAMERA, REAR BUMPER REVERSE SENSOR & ETC. TO EFFECT REPLACE OF REAR TAILGATE & REAR BUMPER	New	60 120.00
3	TO REMOVE & REPLACE & REFIT REAR TAILGATE INNER MECHANISM SUCH AS REAR TAILGATE INNER LOCK, REAR WIPER ARM, REAR TAILGATE TRIM, REAR TAILGATE SPOILER & ETC. TO EFFECT REPLACE OF REAR TAILGATE	New	100 200.00
4	TO REMOVE & REFIT & REPLACE REAR SIDE GLASS LH, REAR SIDE GLASS SEALANT LH & ETC. TO EFFECT REPLACE OF REAR QUATER PANEL LH	New	60 80.00
5	TO REMOVE & REPLACE & REFIT REAR LUGGAGE SIDE TRIM, REAR SPARE TYRE UPPER BOARD, REAR SIDE GLASS UPPER TRIM & ETC. TO EFFECT REPLACE OF REAR QUATER PANEL LH & ETC	New	80 150.00
6	TO REMOVE & REPLACE, REPAIR, READJUST & CHISEL ACCIDENT AREAS SUCH AS REAR TAILGATE, REAR END PANEL, REAR SPARE TYRE PANEL, REAR BUMPER, REAR BUMPER LIP, REAR QUATER PANEL LH, REAR DOOR LH, FRONT BUMPER & ETC. BACK TO ORIGINAL CONDITIONS	New	1200 1,200.00
7	TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, REAR TAILGATE, REAR END PANEL, REAR BUMPER SPARE TYRE PANEL, REAR BUMPER, REAR TAILLAMP PANEL LH, REAR QUATER PANEL LH & REAR DOOR LH	New	1400 1,400.00
8	TO CHECK WIRING & ELECTRICAL SYSTEM	New	40 80.00
9	TO DIAGNOSIS FAULTY CODE & RESET MEMORY	New	100 150.00
Gross Labour Cost (S\$)			3,900.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Paul
Hp 960 100 68
12 days
P/P
24/05/23 @ 1530
Resy before paint