



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23005267/Knp3e2 Date: 07/06/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBJ 9316D	Veh. Inspected	SND 3622Z
Policy No.	D22099240	Coverage (\$)	0.00
Claim No.	D23001752MFCV	Excess (\$)	0.00
Assign From	JOANNE TAN JO ANN	Assign Date	23/05/2023
2. Vehicle Particulars & Condition			
Make & Model	B.M.W. 640I (A)	c.c	2979
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WBA6A02040DZ11829	Colour	MATT GREY
Odometer	133770 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/40 R19	URCOLA	7 mm
L/H Front Tyre	245/40 R19	URCOLA	7 mm
R/H Rear Tyre	275/35 R19	URCOLA	7 mm
L/H Rear Tyre	275/35 R19	URCOLA	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/05/2023	Inspection Date	23/05/2023
Survey held at	YEE AUTO PTE LTD 160 SIN MING DRIVE #02-17 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	