



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 3284C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	SERVICEABLE	579.20	-
1	FRONT BUMPER SIDE RETAINER LH	SERVICEABLE	20.40	-
1	FRONT HEADLAMP LH	SERVICEABLE	668.20	-
1	FRONT HEADLAMP LOWER BRACKET LH	SERVICEABLE	38.40	-
1	FRONT HEADLAMP TOP CHROME LH	SERVICEABLE	95.80	-
1	FRONT SIGNAL LAMP LH	CRACKED	46.50	46.50
1	FRONT FENDER LH	BENT	450.80	450.80
1	FRONT FENDER INNER SHIELD LH	SERVICEABLE	78.20	-
	LESS 20% DISCOUNT		-395.50	-99.46
			1,582.00	397.84
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET FRONT FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	50.00	-
			100.00	-
<b><u>LABOUR</u></b>				
	SPRAY PAINT ON ALL AFFECTED AREA .		800.00	200.00
	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK ,JACK,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA .		800.00	200.00
	TO CHECK WIRING SYSTEM.		100.00	20.00
	TO APPLY ANTI RUST TREATMENT.		120.00	30.00
	TO CHECK & ADJUST WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
			1,920.00	450.00
<b>GRAND TOTAL</b>			<b>3,602.00</b>	<b>847.84</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>847.84</b>

Report Ref No. CS/AGI23005275/Kvp3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.