

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Richard Ang Wei Guang

Date: 06 Jun 2023

Preliminary Advice

Insured Vehicle No : SJX5284U
TP Vehicle No : SJA9164C
Make : TOYOTA COROLLA
Date of Inspection : 25/05/2023
Inspection At : AUTHORIZE WORKSHOP PTE LTD (HQ)
160 SIN MING DRIVE, #03-19 SIN MING AUTOCITY
SINGAPORE 575722
Accident Date : 23/05/2023
Assignment Date : 25/05/2023
Est. Duration of Repair : 6

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,758.21
Revised Amount	:S\$	7,280.65
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,280.65
Lump Sum Repair	:S\$	5,800.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	43,000.00
COE / PARF Rebate	:S\$	18,955.00
Salvage Value	:S\$	
Margin for Repair	:S\$	24,045.00

Remarks

- () The vehicle is economical for repair
() The vehicle is not economical for repair
() Part-by-Part repair
(X) Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.