

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23005294/UNP3M4**Date:** 04/07/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00043092301
Claimant Vehicle No :	SMG4651D	Insured Vehicle No :	XD2262S
Date of Loss:	23/05/2023	Nature of Claim: TP	Claim No: SNM23D203685/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG4651D	Engine No:	2ZR6886814
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 S (A)	Chassis No:	ZVW506052111
Reg. Date:	20/12/2018 (Man. Year: 2016)	Odometer:	259566 km
Colour:	Grey		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 ZR18	Rear Tyre Size:	225/40 ZR18
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,253.71	5,402.27	9,851.44	64.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,560.00	1,580.00	1,980.00	55.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,813.71	6,982.27	11,831.44	62.89
Approved Total (Overridden) (\$\$)		5,500.00		
Nett Amount (\$\$)	18,813.71	5,500.00	13,313.71	70.77

INSPECTION

Date of Assignment:	16/06/2023		
Date Inspected:	25/05/2023	Inspected At:	ZOOM AUTOWERKS PTE LTD BLK 15 KAKI BUKIT RD 4 #01-53 SINGAPORE 417808
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jul 2023)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG4651D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	938.00 FL	*938.00 FL
2	2		*FRONT BONNET HINGES	Bent	116.60 FL	*116.60 FL
3	1		*FRONT BONNET INSULATOR	Torn	243.60 FL	*243.60 FL
4	1		*FRONT BONNET LOCK	Twisted	133.00 FL	*133.00 FL
5	1		*FRONT BONNET RUBBER	Not Necessary	61.20 FL	*- FL
6	1		*FRONT HEADLAMPS	N/S Cracked/ O/S Not Necessary	5,116.00 FL	*1,655.10 FL
7	1		*FRONT GRILLE	Distorted	356.00 FL	*356.00 FL
8	1		*FRONT BUMPER	Distorted	1,339.78 FL	*781.20 FL
9	2		*FRONT BUMPER FOG LAMPS	Not Necessary	710.40 FL	*- FL
10	2		*FRONT BUMPER FOG LAMP COVERS	Not Necessary	137.06 FL	*- FL
11	1		*FRONT BUMPER INNER SPONGE	Torn	72.00 FL	*72.00 FL
12	1		*FRONT BUMPER INNER RETAINER	Bent	165.00 FL	*165.00 FL
13	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	692.00 FL	*- FL
14	2		*FRONT BUMPER REINFORCEMENT STAYS	Not Necessary	310.00 FL	*- FL
15	2		*FRONT BUMPER SIDE RETAINERS	Necessary	154.00 FL	*154.00 FL
16	2		*FRONT BUMPER TOW HOOK COVERS	Not Necessary	157.00 FL	*- FL
17	1		*FRONT BUMPER LOGO	Scratched	88.00 FL	*88.00 FL
18	2		*FRONT FENDERS	Repair	1,866.00 FL	*- FL
19	2		*FRONT FENDER INNER SHIELDS	Not Necessary	307.56 FL	*- FL
20	2		*FRONT FENDER EMBLEMS	Not Necessary	92.82 FL	*- FL
21	1		*FRONT SUPPORT PANEL	Bent	1,266.80 FL	*845.10 FL
22	1		*HORN	Not Necessary	89.50 FL	*- FL
23	1		*AIR CON CONDENSER	Bent/Punctured	1,246.10 FL	*1,246.10 FL
24	1		*RADIATOR	Not Necessary	1,841.00 FL	*- FL
25	1		*RADIATOR FAN BLADE	Not Necessary	211.50 FL	*- FL
26	1		*RADIATOR FAN COWLING	Not Necessary	254.40 FL	*- FL
27	1		*RADIATOR FAN MOTOR	Not Necessary	492.10 FL	*- FL
28	1		*RADIATOR TOP HOSE	Not Necessary	48.50 FL	*- FL
29	1		*FRONT SUPPORT PANEL TOP GARNISH	Twisted	276.00 FL	*276.00 FL
30	1		*AIR CLEANER BOX	Not Necessary	829.10 FL	*- FL
31	1		*AIR INTAKE DUCT	Not Necessary	185.00 FL	*- FL
32	1		*WIPER TANK	Not Necessary	195.60 FL	*- FL
33	1		*SET FRONT BONNET INSULATOR CLIP	Necessary	50.00 FS	*50.00 FS
34	1		*SET FRONT BUMPER CLIP	Necessary	60.00 FS	*50.00 FS
35	1		*FRONT NUMBER PLATE WITH HOLDER	Serviceable	50.00 FS	*- FS
36	2		*SET FRONT FENDER INNER SHIELD CLIPS	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	20,251.62	7,169.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,997.91	1,767.43
Total Parts (\$\$)	15,253.71	5,402.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	80.00	20.00
2	TO REMOVE, REPLACE AIR-CON CONDENSER, REFILL GAS & CONDUCT LEAKAGE TEST	New	180.00	100.00
3	TO APPLY UNDERCOATING	New	200.00	60.00
4	PANEL BEATING	New	1,600.00	600.00
5	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	800.00
Gross Labour Cost (\$\$)			3,560.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >