

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189
Email: mirage1195@gmail.com Mobile: 9061 0543

ACCIDENT VEHICLE INSPECTION REPORT

Report no : 109M0323.PMG
Vehicle no : GBL7620C

1 REFERENCE

Date of inspection : 27 March 2023
Requested by : Westcoast Garage
10 Kaki Bukit Road 2
#03-10 First East Centre
Singapore 417868
Type of survey : Independent
Repairer : Polymath Garage
1 Kaki Bukit Ave 6, #01-15 AutoBay @ Kaki Bukit, Singapore 417883
Date of accident : 25March 2023

2 VEHICLE DATA

Make/model : **NISSAN NV350 URVAN PANEL VAN 5MT**
Chassis no : JN1MA2E26Z0000418
Engine no : QR20020948R
Date of registration : 28 March 2022 *COE Expiry Date:* 27 March 2032
Engine capacity : 1998 cc
Odometer reading : 11327 km
Colour : Grey

3 STATIC CONDITION CHECK

Steering : Serviceable
Foot brakes : Serviceable
Hand brakes : Serviceable
Paintwork : Good
General Condition : Good

4 TIRE CONDITION CHECK

	<u>RH/MAKE</u>	<u>LH/MAKE</u>	<u>SIZE</u>
Front tread	: 8 mm/Yokohama	8 mm/Yokohama	195R15
Rear tread	: 8 mm/Yokohama	8 mm/Yokohama	195R15

5 BRIEF DESCRIPTION OF DAMAGE

Rear bumper scraped/cut/deformed, rear RH outer panel bent, etc. Please see para. 8 of this report for more details.

6 REMARKS

This inspection is carried out on a "WITHOUT PREJUDICE" basis and I have not authorized any repairs.

7 RECOMMENDATION

Cost of repairs : **\$1,500.00** (lump sum)
Estimated no of days : **Four (4)**

8 ASSESSMENT OF DAMAGE AND COSTS

Report no: 109M0323.PMG
 Vehicle no: GBL7620C

A SPARE PARTS

<u>Description</u>	<u>Qty</u>	<u>Assessed Condition</u>	<u>Repairer's Amount</u>	<u>Revised Amount</u>
<u>(Nett Item)</u>				
Rear bumper cover	1	scraped/cut/deformed	642.50	642.50 ✓
Rear bumper side retainer	2	necessary	36.40	36.40 ✓
Rear RH outer panel	1	to repair	3,645.90 R	0.00 X
		Subtotal of the above	4,324.80	678.90
		Discount	10% / 10% 432.48	67.89
		<i>Subtotal 1:</i>	3,892.32	611.01
<u>(Special nett)</u>				
Rear bumper clip	8	necessary	32.00	32.00
		<i>Subtotal 2:</i>	32.00	32.00 ✓
		Total cost of parts:	3,924.32	643.01

B LABOUR

To check wiring.			60.00	30	45.00
To remove and reinstall reverse sensors and check operating functions.			80.00	30	60.00
To apply anti-rust undercoat.			60.00		30.00 ✓
Labour charges to remove and replace, to cut and weld, to panel beating affected and damaged parts.			750.00		500.00 ✓
Spray painting charges to paint the rear bumper, rear RH outer panel and necessary areas.			750.00		500.00 ✓
		Total cost of labour:	1,700.00		1,135.00
		Total cost of repair:	5,624.32		1,778.01

1733.01

4 days

L/S - 1386.40
 = 1400