



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBL 7620C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER COVER	SCRAPED/ CUT/ DEFORMED	642.50	642.50
2	REAR BUMPER SIDE RETAINER	NECESSARY	36.40	36.40
1	REAR RH OUTER PANEL	TO REPAIR SEE LABOUR	3,645.90	-
	LESS 10% DISCOUNT		-432.48	-67.89
			3,892.32	611.01
SPECIAL NETT ITEMS				
8	REAR BUMPER CLIP (SN)	NECESSARY	32.00	32.00
			32.00	32.00
LABOUR				
	TO CHECK WIRING.		60.00	30.00
	TO REMOVE AND REINSTALL REVERSE SENSORS AND CHECK OPERATING FUNCTIONS.		80.00	30.00
	TO APPLY ANTI-RUST UNDERCOAT.	NOT NECESSARY	60.00	-
	LABOUR CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO PANEL BEATING AFFECTED AND DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR RH OUTER PANEL.		750.00	400.00
	SPRAY PAINTING CHARGES TO PAINT THE REAR BUMPER, REAR RH OUTER PANEL AND NECESSARY AREAS.		750.00	400.00
			1,700.00	860.00
GRAND TOTAL			5,624.32	1,503.01
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,200.00

Report Ref No. CS3/AIG23003203/Wvp3m4-1

MUHAMMAD AKID BIN MOHAMED KAMAL

Asst. Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.