| (08/11/13) wef  ASS. REC. BY: Marcus  REF:   | HSB23004318/Upg3  |
|--|---|
|  | SSIGNMENT   |
| Ď.t.   | Veh No: 636 5307 Yr Regn: 31/05-11                                  |
| From: Date:                                  | Type: M.Car / M.Cycle / Bus / Van / Loppy / Taxi / Prime Mover /    |
| Estimated Cost:                              | Truck / Trailer or (M)  |
| To inspect Vehicle No:                       | 1                             |
| 2 1 1  | - /   |
| at Workshop m/s 2 M Auc                      |   |
| of   | 108/1   |
| Insured: SM 79504                            | Eng/No:   |
| Policy No.                                   | C/NO: JNISC 27 2420859649   |
| Claims No.                                   | Gen. Cond: Good / Fair / Poor / Burnt                               |
| Sum Insured: Excess:                         | Steering: Increer / Jammed / Leaked / Burnt or                      |
| (Client's Record)                            | Brake: Inforder / Jammed / Leaked / Burnt or                        |
| Make of Veh:                                 | Modi: (Nil ) S/Rim / STD A/Rim or  Tyre Size: F: /95-7/             |
| 1  | 1,100 0.20.   |
| (Policy Condition)                           | R: 165-113  |
|  | BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /     |
| repair at the time of inspection.            | TOYO/YOKO or ZAULU  |
| Bal. or Market Value:                        | Front Rear  |
| IDAC Accident Rport: Consistent? : Yes or No | R/Bal. 6 6 mm   |
| GIA / PR Seen: Consistent?: Yes or No        | L/Bal. 6 mm L/Bal. 6/6 mm   |
| Est. Repairs: days Res.: Yes or No           | D.O.A. 22/05/23 D.O.I. 25/05/23                                     |
| Lum Sum: 20 % 3 Val.: Yes or No              | Survey held at  |
| CA / REV / REP. / 24 HRS + C 324N            | Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or         |
| , Vehicle: IN / C                            | DUT NIS FM.   |
| Date: Person Contacted: L714@17              | The U/C / Chassis frame / Body Structure affected due to collision. |
| Date / Time Action / Instruction             |   |
| 10/23 He 53/00 10 for 12                     | AH long   |
| 013/0) /3 \$ 3100 111/0/00                   |   |
|  |   |
|  |   |
|  |   |
|  |   |
|  |   |
| Date/Time, File Pass to? : Preli. Report     | Days Of Repair:   |
| 1) : Final Report                            | Resurvey No. of Trip: Survey Fee:                                   |
| Date/Time, File Return to?                   | Transportation:   |
| 2) Add I                                     |   |
|  | : Interview (\$ ) Photos  |
| Report Format :                              | : Tech. Invs (\$ ) Others   |
| Lump Sum / I.B.I: (\$)                       | : Weekend (\$   |
|  | TOTAL   |

## 2nd Auto Ptd Ltd

Nissan Cabstar (GBG550T)

## **ESTIMATE VEHICLE COST OF REPAIR**

|     | Net litems                                 |                |
|-----|--|----------------|
| No. | Description ( Parts )                      | Cost of Repair |
| 1   | Front Bumper Assy                          | \$1,180.00     |
| 2   | Front Bumper Reinforcement Inner Center    | \$550.00 ×     |
| 3   | Front Bumper Bracket LH                    | \$120.00 X     |
| 4   | Front Headlamp Assy LH (18-51) SCA         | \$900.00       |
| 4   | Front Headlamp Lower Cover LH 48.20 CU7    | \$300.00       |
| 5   | Front Side Signal Lamp Assy LH 46.50 5 c 1 | \$250.00       |
| 6   | Front Door Assy LH DO 124+                 |                |
| 7   | Front Door Weatherstripe LH                | \$350.00 🗴     |
| 8   | Front Door Weatherstripe Lower LH          | \$300.00 X     |
| 9   | Front Door Side Step Cover LH 262.80 (1)   | \$280.00       |
| 10  | Front Side Bedy Panel LH                   | \$300.00       |
| 11  | Front Side Body Panel Inner LH             | \$350.00 X     |
|     | Total Cost of List Parts / 19 7            | \$6,050.00     |

|     | Special Nett Items                |                                  |            |
|-----|-----------------------------------|----------------------------------|------------|
| No. | Description ( Parts )             |                                  | COST       |
| 1   | Front Bumper Clips & Nuts (1 set) | 11                               | \$100.00   |
| 2   | Front Side Step Clips             | 11                               | \$100.00 🗙 |
|     |                                   | Total Cost of Special Nett Items | \$200.00   |
|     |                                   | TOTAL COST OF PARTS              | \$6,250.00 |

|     | Labour   |             |
|-----|--|-------------|
| No. | Description ( Parts )  | COST        |
| 1   | To cut, weld, straighten affected areas and replace damaged parts.           | \$1,200.00  |
| 2   | To putty and spray painting the affected areas.                              | \$1,200.00  |
| 3   | To check front lighting and wiring.  | \$100.00    |
| 4   | To apply anti rust proofing to the affected areas.                           | \$250.00    |
| 5   | To remove and install front inner garnish and trim to facilitate the repair. | \$200.00 11 |
| 6   | To conduct wheel alignment   | \$250.00 M  |
|     | Total Cost of Labour   | \$3,200.00  |
|     | TOTAL COST OF REPAIR   | \$9,450.00  |

Not Authorid 25/05/23 1/5#3100 3 days. Weght. Att 112-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

38789 202

3107