

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23005328/AQP3Q2**Date:** 14/07/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00035602304		
Claimant Vehicle No :	GBJ964S	Insured Vehicle No :	YP2609B		
Date of Loss:	20/05/2023	Nature of Claim:	TP	Claim No:	SNM23D203670/C02/KHONGLH

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBJ964S</b>	Engine No:	1KD2836732
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Chassis No:	JTFAT35Y70K212238
Reg. Date:	02/01/2019 (Man. Year: 2018)	Odometer:	153588 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195 R15C	Rear Tyre Size:	155 R12C
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,951.27	4,384.80	2,566.47	36.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,250.00	1,860.00	1,390.00	42.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,201.27</b>	<b>6,244.80</b>	<b>3,956.47</b>	<b>38.78</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,201.27</b>	<b>5,000.00</b>	<b>5,201.27</b>	<b>50.99</b>

**INSPECTION**

Date of Assignment:	25/05/2023		
Date Inspected:	26/05/2023	Inspected At:	Heng Kee Workshop (HQ) BLK 1033 EUNOS AVENUE 5A #01-31 Singapore 409703
Estimated Period of Repair:	6.0 days		

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 14 Jul 2023)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ964S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE LAMP	Not Necessary	69.60 FL	*- FL
2	1		*REAR NUMBER PLATE PANEL	Bent	160.40 FL	*160.40 FL
3	1		*TAILLAMP	Cut	255.40 FL	*255.40 FL
4	1		*TAILLAMP PANEL	Bent	185.50 FL	*185.50 FL
5	1		*STOPPER BRACKET	Bent	153.20 FL	*153.20 FL
6	1		*TAILGATE	Dented	1,482.50 FL	*1,482.50 FL
7	1		*TAILGATE SIDE LOCK	Damaged	160.50 FL	*160.50 FL
8	2		*TAILGATE HINGE	Bent	131.00 FL	*131.00 FL
9	1		*TAILGATE LOWER PANEL	Repair	495.60 FL	*- FL
10	1		*TAILGATE TOYOTA STICKER	Necessary	176.50 FL	*176.50 FL
11	1		*SIDE GATE	Dented	1,881.40 FL	*1,881.40 FL
12	2		*SIDE GATE LOWER PANEL	Repair	1,663.00 FL	*- FL
13	1		*SPARE TYRE LOCK REGULATOR	Not Necessary	283.10 FL	*- FL
14	1		*REAR EXHAUST PIPE	Not Necessary	486.50 FL	*- FL
15	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	45.10 FL	*- FL
16	1		*REAR EXHAUST PIPE GASKET	Not Necessary	32.40 FL	*- FL
17	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
18	1		*REAR STEP PANEL	Bent	350.00 FS	*250.00 FS
19	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
20	1		*STOPPER	Cut	40.00 FS	*40.00 FS
21	1		*TAILGATE INNER METAL PANEL	Dented	380.00 FS	*300.00 FS
22	1		*SET TAILGATE INNER METAL PANEL RIVETS	Necessary	50.00 FS	*50.00 FS
23	1		*DYNA STICKER	Necessary	45.00 FS	*45.00 FS
24	1		*70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
25	1		*13 PAX STICKER	Necessary	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,866.70	5,531.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,915.43	1,146.60
Total Parts (\$\$)	6,951.27	4,384.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ,REMOVE AND REFIT PARTS	New	1,400.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	800.00
3	WIRING CHECK	New	50.00	30.00
4	TUFF COAT	New	150.00	80.00
5	TO REMOVE REAR EXHAUST PIPE	New	150.00	0.00
6	TO REMOVE REVERSE SENSOR	New	100.00	50.00
7	TO REMOVE SIDE GATE TOP RAILING	New	200.00	100.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,250.00</b>	<b>1,860.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >