

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG23005332/DQP3E2  
**Date:** 11/07/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002562692
<b>Claimant Vehicle No :</b>	SJS3367D	<b>Insured Vehicle No :</b>	FBL2077D
Date of Loss:	29/04/2023	Nature of Claim:	TP
		Claim No:	314503

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJS3367D</b>	Engine No:	3ZZ4918773
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106151341
Reg. Date:	12/08/2009 (Man. Year: 2009)	Odometer:	136123 km
Colour:	Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	16,710.70	7,747.12	8,963.58	53.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,260.00	2,010.00	2,250.00	52.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,970.70</b>	<b>9,757.12</b>	<b>11,213.58</b>	<b>53.47</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>20,970.70</b>	<b>7,800.00</b>	<b>13,170.70</b>	<b>62.81</b>

INSPECTION

Date of Assignment:	25/05/2023	Alfred Auto Services & Supplies (HQ)
Date Inspected:	25/05/2023 Inspected At:	Blk 5035, Ang Mo Kio Ave 3, #01-351, Ang Mo Kio Industrial Park 2
Estimated Period of Repair:	7.0 days	Singapore 569538

**Adjuster:** BRYAN TANI**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 30 Jun 2023)
<b>Parts:</b> 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJS3367D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	991.00 F	*756.90 FL
2	2		*BONNET HINGE	Bent	396.00 F	*156.00 FL
3	1		*BONNET LOCK	Bent	298.60 F	*148.30 FL
4	1		*BONNET RUBBER	Necessary	192.30 F	*38.00 FL
5	1		*BONNET STOPPER	Not Necessary	28.00 F	*- FL
6	1		*FENDER LH	Dented	610.00 F	*498.10 FL
7	1		*FENDER LH SIDE RETAINER	Dislodged	189.20 F	*189.20 FL
8	1		*FENDER DUST GARNISH	Dislodged	288.90 F	*126.40 FL
9	10		*FENDER DUST GARNISH CLIP	Necessary	80.00 FS	*15.00 FS
10	1		*WIPER GARNISH CLIP	Not Necessary	398.60 F	*- FL
11	1		*SIDE MIRROR LH ASSY	Broken	1,130.00 F	*867.80 FL
12	1		*AIR BOX HOSE	Broken	199.50 F	*199.50 FL
13	2		*HEAD LAMP RH/LH	Broken	1,396.60 F	*1,087.80 FL
14	1		*SUPPORT PANEL	Bent	890.00 F	*708.40 FL
15	1		*SUPPORT LOWER GARNISH	Broken	305.00 F	*193.10 FL
16	1		*FRONT BUMPER	Torn	795.50 F	*566.10 FL
17	1		*FRONT BUMPER REINFORCEMENT	Dented	489.60 F	*358.10 FL
18	1		*FRONT BUMPER LOWER GRILLE	Dislodged	310.00 F	*133.10 FL
19	1		*FRONT BUMPER FOG LAMP N/S	Dislodged	480.60 F	*210.40 FL
20	1		*FRONT BUMPER FOG LAMP COVER N/S	Dislodged	198.50 F	*198.50 FL
21	10		*FRONT BUMPER CLIP	Necessary	60.00 FS	*20.00 FS
22	1		*FRONT GRILLE	Broken	531.00 F	*287.70 FL
23	1		*FRONT GRILLE LOGO	Necessary	125.60 F	*68.10 FL
24	1		*FRONT LH WHEEL HOUSING GARNISH	Deformed	302.80 F	*108.30 FL
25	4		*FRONT GRILLE CLIP	Necessary	24.00 FS	*12.00 FS
26	1		*RADIATOR	Bent / Broken	836.50 F	*836.50 FL
27	1		*AIR-CON CONDENSER	Bent	599.80 F	*599.80 FL
28	1		*WINDSCREEN	Cracked	1,130.00 F	*785.40 FL
29	1		*WINDSCREEN MOULDING	Necessary	298.00 F	*120.30 FL
30	1		*WINDSCREEN INNER SEAL	Necessary	80.00 FS	*40.00 FS
31	1		*WINDSCREEN SEALANT & REPAIR KIT	Not Necessary	180.00 FS	*- FS
32	1		*NUMBER PLATE & BOX	Dislodged	50.00 FS	*45.00 FS
33	1		*AIR CHAMBER BOX	Broken	598.80 F	*358.10 FL
34	1		*WIPER ARM	Broken	199.00 F	*199.00 FL
35	1		*WIPER BLADE	Broken	42.00 FS	*42.00 FS
36	1		*BONNET SPONGE	Torn	410.50 F	*217.30 FL
37	10		*BONNET SPONGE CLIPS	Necessary	60.00 FS	*15.00 FS
38	1		*HI BEAM BULB	Not Necessary	95.00 F	*- FL
39	1		*HI BEAM WIRE BRACKET	Not Necessary	40.00 F	*- FL
40	1		*LOW BEAM BULB	Not Necessary	90.00 F	*- FL
41	1		*SMALL LAMP BULB	Not Necessary	20.00 F	*- FL
42	1		*FOG LAMP BULB	Not Necessary	51.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*LH LOWER WHEEL HOUSING DUST GARNISH	Not Necessary	210.00 F	*- FL
44	1		*VVTI EMBLEM	Necessary	68.80 F	*61.30 FL
45	1		*SPORT RIM	Not Necessary	550.00 F	*- FL
46	1		*TYRE	Not Necessary	390.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>16,710.70</b>	<b>10,266.50</b>
<b>- List Item Discount on L Items 0.00/25.00% (S\$)</b>	0.00	2,519.38
<b>Total Parts (S\$)</b>	<b>16,710.70</b>	<b>7,747.12</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REFIT FRONT SUPPORT PANEL WIRING, CHECK HEAD LAMP WIRING & RENEW PARTS	New	200.00	30.00
2	TO REMOVE & REFIT, RENEW AIR-CON CONDENSER, TOP-UP GAS & OIL	New	180.00	120.00
3	TO WELDING, KNOCKING, STRAIGHTENING REPAIR & RENEW ALL ACCIDENT DAMAGED AFFECTED AREA	New	1,600.00	800.00
4	TO RESPRAY PAINTING ON INNER & OUTER PORTION & ALL ACCIDENT AFFECTED AREA	New	1,800.00	900.00
5	TO RUST PROOF ALL ACCIDENT AFFECTED AREA	New	120.00	40.00
6	TO REMOVE & RENEW FRONT WINDSCREEN & VACUUM, CLEANING DAMAGED GLASS	New	180.00	120.00
7	TO REMOVE & RENEW TYRE, SPORT RIM & BALANCING. HEADLAMP WIRING & RENEW PARTS	New	180.00	0.00
			<b>Gross Labour Cost (\$\$)</b>	<b>4,260.00</b>
				<b>2,010.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >