

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 30 Jun 2023

**Preliminary Advice**

Insured Vehicle No	: FBL2077D	Accident Date	: 29/04/2023
TP Vehicle No	: SJS3367D	Assignment Date	: 25/05/2023
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 7
Date of Inspection	: 25/05/2023		
Inspection At	: ALFRED AUTO SERVICES & SUPPLIES (HQ) BLK 5035, ANG MO KIO AVE 3, #01-351, ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569538		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,970.70
Revised Amount	:S\$	9,757.13
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,757.13
 Lump Sum Repair	:S\$	 7,800.00

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	60,000.00
COE / PARF Rebate	:S\$	15,290.00
Salvage Value	:S\$	
Margin for Repair	:S\$	44,710.00

**Remarks**

- ( ) The vehicle is economical for repair  
 ( ) The vehicle is not economical for repair  
 ( ) Part-by-Part repair  
 ( X ) Lump Sum repair
- ( X ) The above survey was conducted on a 'without prejudice' basis.  
 Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.