

A.S. P.C. BY:

REF:

CS/MSG 23005332/D9P3

ASSIGNMENT

COE April 2029

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S

Bel. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repair: 7 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJS 3367D Yr Regn: Ang / 2009

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota ~~Vitz~~ ALTIS C.C. _____

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 136123 T/Radio: Insured / Std / NI / NA

Eng/No: 3224918773

C/No: MR0532BE106151341

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____ R: _____

195/65 R15
" "

BS / DUN / EXNOVA / GY / FS / LZA / NIG / OHTSU / PIR / SUMI /

TOYO / YOKO or Dunlop

Front R/Bal: 5 mm Rear R/Bal: 5 mm

L/Bal: 5 mm L/Bal: 5 mm

D.O.A. 29/04/2023 D.O.L. 25/05/2023

Survey held at Applied Auto

Des. of Damages: Frit / Rear / O/S / N/S / U/C / Rooftop or

Rent H/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MSG FBL 2077D
	MV 60K
	LFA 15.2K
	L 44.8K
<u>27/06/23</u>	To seek quote H/S 7,800/- with 7 days of gap. (Red @ 13170.70, 63%)

Date/Time, File Pass to? : Prel. Report : Final Report

1) _____
2) _____

Report Format: _____

1 series 2 series 1 & 2 to 1/2

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Invs (\$)

Survey Fee:	
Transportation:	S + RS \$
Photos:	
Other:	



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
 Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
 Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference No.: 240523

Date: 24.05.2023

Yeo Chun Yang Vernon
 Blk 275 Yishun St 22 #10-128
 Singapore 760275.

Toyota Altis 1.6

Estimate Repair Cost for Vehicle Reg. No: SJS 3367 D

1 Pc. Bonnet <i>Dented</i>	991.00	✓	756.90
2 Pcs. Bonnet Hinge <i>BT</i>	396.00	✓	156.00
1 Pc. Bonnet Lock <i>BT</i>	298.60	✓	148.30
1 Pc. Bonnet Rubber <i>Hee</i>	192.30	✓	38.00
1 Pc. Bonnet Stopper <i>HH</i>	28.00	X	
1 Pc. Fender LH <i>Dented</i>	610.00	✓	498.10
1 Pc. Fender LH Side Retainer <i>Hee broken dislodged</i>	189.20	✓	
1 Pc. Fender Dust Garnish <i>dislodged</i>	288.90	✓	126.40
10 Pcs. Fender Dust Garnish Clip <i>Hee</i>	80.00	✓	15.00 SH @ 8.00
1 Pc. Wiper Garnish Clip <i>HH</i>	398.60	X	
1 Pc. Side Mirror LH Assy. <i>broken</i>	1,130.00	✓	867.80
1 Pc. Air Box Hose <i>broken</i>	199.50	✓	
2 Pcs. Head Lamp RH/LH <i>broken</i>	1,396.60	✓	1087.80 @ 698.30
1 Pc. Support Panel <i>BT</i>	890.00	✓	708.40
1 Pc. Support Lower Garnish <i>broken</i>	305.00	✓	193.10
1 Pc. Front Bumper <i>to m</i>	795.50	✓	566.10
1 Pc. Front Bumper Reinforcement <i>Dented</i>	489.60	✓	358.10
1 Pc. Front Bumper Lower Grille <i>dislodged</i>	310.00	✓	133.10
1 Pc. Front Bumper Fog Lamp <i>dislodged Hee</i>	480.60	✓	210.40
1 Pc. Front Bumper Fog Lamp Cover <i>dislodged Hee</i>	198.50	✓	
10 Pcs. Front Bumper Clip <i>Hee</i>	60.00	✓	20.00 SH @ 6.00
1 Pc. Front Grille <i>broken</i>	531.00	✓	287.70
1 Pc. Front Grille Logo <i>Hee</i>	125.60	✓	68.10
1 Pc. Front LH Wheel Housing Garnish <i>broken damaged</i>	302.80	✓	108.30
4 Pcs, Front Grille Clip <i>Hee</i>	24.00	✓	12.00 SH @ 6.00
1 Pc. Radiator <i>Auto Hee / broken</i>	836.50	✓	
1 Pc. Air-con Condenser <i>BT</i>	599.80	✓	
1 Pc. Windscreen <i>CRAC</i>	1,130.00	✓	785.40
1 Pc. Windscreen Moulding <i>Hee</i>	298.00	✓	120.30
1 Pc. Windscreen Inner seal <i>Hee</i>	80.00	✓	40.00 SH



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre & Sports Rim



1 Pc. Windscreen Sealant & Repair Kit	180.00 (S.Nett) X
1 Pc. Number Plate & Box <i>disbanded</i>	50.00 45/- SH

Total (Panels / Parts): 13,885.60 (SGD)

SH 132.00 =

List 9,241.80
25% 6,931.35 =

LABOR CHARGES

To remove & refit front support panel wiring, check Head lamp wiring & renew parts. 200.00 30/-

To remove & refit, renew air-con condenser, top-up Gas & oil. 180.00 120/-

To welding, knocking, straightening repair & renew All accident damaged affected area. 1,600.00 800/-

To respray painting on inner & outer portion & all Accident affected area. 1,800.00 900/- 2010.00 =

To rust proof all accident affected area. 120.00 40/-

To remove & renew front windscreen & vacuum, Cleaning damaged glass. 180.00 120/-

Total (Labor Charges): 4,080.00 (SGD)

25/05/2022 @ 1730hr
NAJ Jahan

7 dgs.

TOTAL COST SUMMARY

PANELS / PARTS	13,885.60	9073.35
LABOR CHARGES	4,080.00	Supp 683.77

Grand Total: 17,965.60 (SGD)

9,757.12

Check repair limit. 4/5 7,800/-

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre & Sports Rim



Reference No.: 240523

Date: 24.05.2023

Yeo Chun Yang Vernon
Blk 275 Yishun St 22 #10-128
Singapore 760275.

Toyota Altis 1.6

Supplementary Repair Cost for Vehicle Reg. No: SJS 3367 D

1 Pc. Air Chamber Box <i>broken</i>	598.80	✓	358.10
1 Pc. Wiper Arm <i>broken</i>	199.00	✓	
1 Pc. Wiper Blade <i>broken</i>	42.00	✓	SH
1 Pc. Bonnet Sponge <i>turn</i>	410.50	✓	217.30
10 Pcs. Bonnet Sponge Clips <i>HCC</i> @ 6.00	60.00	✓	15.00 SH
1 Pc. Hi Beam Bulb <i>HN</i>	95.00	X	
1 Pc. Hi Beam Wire Bracket <i>HN</i>	40.00	X	
1 Pc. Low Beam Bulb <i>HN</i>	90.00	X	
1 Pc. Small Lamp Bulb <i>HN</i>	20.00	X	
1 Pc. Fog Lamp Bulb <i>HN</i>	51.00	X	
1 Pc. LH Lower Wheel Housing Dust Garnish <i>HN</i>	210.00	X	
1 Pc. VVTi Emblem <i>HCC</i>	68.80	✓	61.30
1 Pc. Sport Rim <i>HN</i>	550.00	X	
1 Pc. Tyre <i>HN</i>	390.00	X	

Total (Panels / Parts): 2,825.10 (SGD)

835.70

25% 626.77 =

LABOR CHARGES

To remove & renew tyre, sport rim & balancing.
Head lamp wiring & renew parts.

180.00 *HN*

SH 57.00 =

Total (Labor Charges): 180.00 (SGD)

29/05/2023 @ 1030m

Yc

2kk auto

683.77