



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23005337/Tnp3m4 Date: 26/07/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SG 6080S	Veh. Inspected	SMB 3124S
Policy No.	D-22099187MFBP	Coverage (\$)	0.00
Claim No.	D23000925MFBP	Excess (\$)	0.00
Assign From	AINI BINTE	Assign Date	24/05/2023
2. Vehicle Particulars & Condition			
Make & Model	MAN NL 320F	c.c	10518
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WMAA22ZZ0F7002667	Colour	GREEN
Odometer	503775 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm
L/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm
R/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm
L/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S MIRROR. DAMAGES SEE DETAILS			
5. General Information			
Accident Date	14/03/2023	Inspection Date	25/05/2023
Survey held at	3 YIO CHU KANG ROAD S(786010) (SELETAR DEPOT)		
Repairer	SBS TRANSIT LTD (Branch)		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	