

ASS. REC. BY: Tajir

REF: _____

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen _____ Consistent? : Yes or No

Est. Repairs _____ days Res.: Yes or No

Lump Sum _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT
NurizmanVeh No: SMB31245 Yr Regn: 2015 / May

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAN NL320F C.C. 10518Colour: Green A/C: Insured / Std / NI / NASp. Reading: 533775 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WM4A22770F 7002667

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: N/S / Rim / STD A/Rim orTyre Size: F: 245/70R22.5R: ~ ~ (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm R/Bal. 8/8 mmL/Bal. 8 mm L/Bal. 8/8 mmD.O.A. _____ D.O.I. 25/5/23Survey held at Selefar bus Dept.

Des. of Damages: Frt / Rear / O/S / N/S / U/G / Rooftop or

O/S Mirror

The U/G / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Rep. Form: _____

Lump Sum / L.R. : _____

Accident Repair Estimate

Accident Date: 14/03/2023

Bus Registration Number: SMB 3124 S

Accident Time: 06 : 50 HRS

Bus Type: MAN A22 EU5, SD, AC, 2 Axle

Accident Report Number: AR-2023-1407

Date of Survey: 25/05/2023

3rd Party Claim against: SG 6080 S

Date of Registration: 04/05/2015

Section A

[illegible]

Section 8

NO.	Assessment/Repair/Spray paint (labour Cost)	
1	TO REMOVE / REPLACE / REPAIR DAMAGE PARTS / ASSESSMENT BY WORKSHOP	\$ 188.00
2	TO REMOVE / REPLACE / REPAIR DAMAGE PARTS BY CONTRACTOR	\$ -
3	TO REMOVE / REPLACE / REPAIR DAMAGE ADVERTISEMENT/GREEN LIVERY PANEL	\$ -
	Total Labour Cost	\$ 188.00

Section C

NO.	Summary		
1	TOTAL REPAIR COSTS		\$ 732.00 ✓
2	TOTAL DOWNTIME (DAYS)	1	\$ 378.66 DAILY RATE-WSD=\$378.66 ✓
3	TOWING COST		\$
4	TOTAL OVERHEADS COSTS = TOTAL REPAIR COST x 30%		\$ 219.60 Xnn
	TOTAL COST		\$ 1,330.26

SURVEYOR ACCEPTANCE

NAME: _____
DATE: _____
SIGN: _____
HP NO: _____
E-MAIL: _____
COMPANY: _____

SBST VERIFICATION

Nurizman Yusoff
Technical Officer
(DID) 63754264/ (HP) 84256323 | nurizmanby@sbstransit.com.sg
Bus Engineering | Seletar Depot
3 Yio Chu Kang crescent(S786010)

SBS Transit



A member of COMFORTALOG

NURIZMAN BIN YUSOFF
TECHNICAL OFFICER
SELETAR BUS WORKSHOP

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfermi 47445744
25/5/23
01 day