

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123005345/UQP3Q2**Date:** 19/06/2023**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : GBK3475L **Insured Vehicle No :** SKR4833L

Date of Loss: 24/05/2023 Nature of Claim: TP Claim No: CDMPG23001278

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBK3475L**

Make & Model: SUZUKI EVERY, 658cc JOIN TURBO 660 (A) Engine No: R06A2707133

Reg. Date: 26/05/2020 (Man. Year: 2020) Chassis No: DA17V854815

Colour: Multi-colour Odometer: 66800 km

Engine Capacity: 658 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 155 R12 Rear Tyre Size: 155 R12

Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,022.00	4,429.30	6,592.70	59.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,590.00	1,340.00	1,250.00	48.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,612.00	5,769.30	7,842.70	57.62
Approved Total (Overridden) (S\$)		4,600.00		
(S\$)	13,612.00	4,600.00	9,012.00	66.21
+ GST 8.00/8.00% (S\$)	1,088.96	368.00	720.96	66.21
Nett Amount (S\$)	14,700.96	4,968.00	9,732.96	66.21

INSPECTION

Date of Assignment: 25/05/2023

Date Inspected: 25/05/2023 Inspected At: Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 19 Jun 2023)	
Parts:	N/A	SUZUKI EVERY 658cc JOIN TURBO 660 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK3475L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,920.00 FL	*1,820.00 FL
2	1		*TAILGATE REAR LOGO	Not fitted	92.00 FL	*- FL
3	1		*TAILGATE EVETY STICKER	Not fitted	80.00 FL	*- FL
4	1		*TAILGATE INNER LOCK	Not Necessary	295.00 FL	*- FL
5	1		*TAILGATE INNER TRIM	Not Necessary	399.00 FL	*- FL
6	1		*TAILGATE INNER PULL GARNISH	Not Necessary	98.00 FL	*- FL
7	1		*TAILGATE OUTER HANDLE	Not Necessary	420.00 FL	*- FL
8	1		*REAR BUMPER	Dented / Deformed	1,120.00 FL	*845.00 FL
9	1		*REAR BUMPER LAMPS	N/S Not Necessary / O/SCracked	640.00 FL	*299.00 FL
10	2		*REAR BUMPER SIDE RETAINERS	Necessary	130.00 FL	*130.00 FL
11	1		*REAR BUMPER UNDER SHIELD N/S	Not Necessary	168.00 FL	*- FL
12	1		*REAR END PANEL OUTER	Repair	566.00 FL	*- FL
13	1		*REAR END PANEL INNER	Not Necessary	595.00 FL	*- FL
14	1		*REAR EXHAUST	Not Necessary	588.00 FL	*- FL
15	1		*REAR SPARE TYRE BRACKET	Not Necessary	291.00 FL	*- FL
16	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
17	1		*REAR WINDSCREEN INNER SEAL	Necessary	40.00 FS	*40.00 FS
18	1		*TAILGATE 70KM/H STICKER	Necessary	10.00 FS	*10.00 FS
19	1		*TAILGATE SEALANT	Necessary	50.00 FS	*50.00 FS
20	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
21	1		*SET TAILGATE MATT STICKER	Necessary	500.00 FS	*300.00 FS
22	1		*SET TAILGATE REAR CARPORATE STICKER	Necessary	1,200.00 FS	*500.00 FS
23	1		*SET REAR BUMPER MATT STICKER	Necessary	500.00 FS	*300.00 FS
24	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
25	1		*SET REAR FENDER MATT STICKER O/S	Not Necessary	800.00 FS	*- FS
26	1		*SET REAR O/S STICKER DECAL	Not Necessary	50.00 FS	*- FS
27	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
28	1		*SET REAR BUMPER REVERSE SENSOR	Malfunction	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,022.00	4,584.00
- List Item Discount on L Items 5.00/5.00% (\$\$)	370.10	154.70
+ Margin on L,N Items 5.00/0.00% (\$\$)	370.10	0.00
Total Parts (\$\$)	11,022.00	4,429.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO R&R REAR REVERSE SENSOR	New	80.00	50.00
3	TO R&R REAR WINDSCREEN	New	120.00	100.00
4	TO R&R TAILGATE MECHANISM	New	100.00	60.00
5	TO R&R CUSHION UPHOLSTERY	New	120.00	0.00
6	TO R&R REAR EXHAUST	New	100.00	0.00
7	TO DIAGNOSTIC & REPROGRAMME SYSTEM	New	120.00	0.00
8	TO SPRAY RUST PROOFING	New	100.00	30.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	800.00	400.00
10	TO PUTTY & SPRAY PAINTING	New	1,000.00	680.00
Gross Labour Cost (S\$)			2,590.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >