

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988

Our File No: CS/EGI23005346/SQP3Q2**Date:** 05/07/2023**REFERENCE**

Insured/Claimant: SYSTEMS ENGINEERING & MARINE PTE. LTD Policy No: DMCG22015494

Date of Loss: 23/05/2023

Nature of Claim: OD

Claim No: CDMCG23001269

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YN9985D**
 Make & Model: ISUZU NPR85UH5A, 3.0 D (M) Engine No: 4JJ11P5559
 Reg. Date: 09/11/2015 (Man. Year: 2014) Chassis No: JAANPR85HE7100759
 Colour: White Odometer: 453829 km
 Engine Capacity: 2999 cc
 Market Value/New Car Price: S\$39,000.00
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/85 R16 Rear Tyre Size: 205/85 R16
 Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm
 Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,322.00	5,903.25	3,418.75	36.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,125.00	2,605.00	6,520.00	71.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,447.00	8,508.25	9,938.75	53.88
Approved Total (Overridden) (\$\$)		6,800.00		
- Excess (\$\$)	800.00	800.00	0.00	0.00
(\$\$)	17,647.00	6,000.00	11,647.00	66.00
+ GST 8.00/8.00% (\$\$)	1,411.76	480.00	931.76	66.00
Nett Amount (\$\$)	19,058.76	6,480.00	12,578.76	66.00

INSPECTION

Date of Assignment: 25/05/2023

Date Inspected: 26/05/2023 Inspected At:

JIT Keong Trading Co. Pte Ltd (HQ)
28 Benoi Place
Singapore 629945

Estimated Period of Repair: 14.0 days

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 05 Jul 2023)	
Parts:	N/A	ISUZU NPR85UH5A 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN9985D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN	Cracked	1,489.00 F	*1,280.00 FL
2	1		*WINDSCREEN TOP MOULDING	Necessary	345.00 F	*196.00 FL
3	1		*WINDSCREEN LOWER MOULDING	Necessary	280.00 F	*142.00 FL
4	2		*WINDSCREEN ADHESIVE SEALANT	Necessary	130.00 F	*50.00 FL
5	1		*L/H WIPER ARM	Dented	178.00 F	*125.00 FL
6	2		*WIPER BLADE	Dented	70.00 F	*70.00 FL
7	1		*WIPER PANEL	Dented	320.00 F	*320.00 FL
8	1		*FRONT PANEL (OUTER)	Buckled	560.00 F	*560.00 FL
9	1		*SET ISUZU LOGO	Necessary	185.00 F	*118.00 FL
10	2		*FRONT PANEL CLIP	Necessary	25.00 F	*25.00 FL
11	2		*FRONT PANEL MOULDING	Necessary	96.00 F	*96.00 FL
12	1		*FRONT GRILLE	Cracked	365.00 F	*365.00 FL
13	1		*FRONT GRILLE CLIP (7 PCS)	Necessary	52.50 F	*20.00 FL
14	1		*FRONT BUMPER ASSEMBLY	Deformed	425.00 F	*425.00 FL
15	1		*FRONT BUMPER REINFORCEMENT BRACKET L/H	Dented	165.00 F	*165.00 FL
16	1		*FRONT BUMPER REINFORCEMENT BRACKET R/H	Not Necessary	165.00 F	*- FL
17	8		*BUMPER CLIP	Necessary	60.00 F	*30.00 FL
18	1		*NUMBER PLATE	Dented	30.00 F	*30.00 FL
19	2		*NUMBER PLATE CLIP	Not Necessary	15.00 F	*- FL
20	1		*FRONT L/H CORNER PANEL	Cracked	248.00 F	*248.00 FL
21	1		*CORNER PANEL MOULDING	Cut	55.00 F	*55.00 FL
22	5		*CORNER PANEL CLIP	Necessary	42.50 F	*15.00 FL
23	1		*CORNER PANEL COVER	Cracked	12.50 F	*12.50 FL
24	1		*FRONT L/H MIRROR ARM	Not Necessary	275.00 F	*- FL
25	1		*FRONT MIRROR ARM COVER	Cracked	12.50 F	*12.50 FL
26	1		*FRONT L/H SIGNAL LAMP ASSY	Cracked	148.00 F	*148.00 FL
27	2		*SIGNAL LAMP CLIP	Necessary	15.00 F	*10.00 FL
28	1		*FRONT L/H HEAD LAMP ASSY	Scratched / Cut	345.00 F	*345.00 FL
29	1		*L/H HEADLAMP LOWER MOULDING	Deformed	13.00 F	*13.00 FL
30	1		*FRONT L/H STEP BOARD	Not Necessary	85.00 F	*- FL
31	1		*FRONT L/H CABIN MOUNTING	Dented	385.00 F	*385.00 FL
32	1		*FRONT MAIN PANEL (INNER)	Dented	1,480.00 F	*729.00 FL
33	1		*AIR CON CASING ASSEMBLY (BLOWER MOTOR)	Cracked	1,250.00 F	*955.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	9,322.00	6,945.00
- List Item Discount on L Items 0.00/15.00% (S\$)	0.00	1,041.75
Total Parts (S\$)	9,322.00	5,903.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR FRONT L/H CHASSIS	New	2,800.00	0.00
2	WELDING ,PANEL BEATING & ALIGNMENT REPAIR AND LABOUR	New	1,800.00	800.00
3	SPRAY PAINTING	New	1,600.00	1,200.00
4	TOP UP AIR CON OIL	New	50.00	30.00
5	TOP UP AIR CON GAS	New	75.00	75.00
6	LIFTING EQUIPMENT TO REMOVE REFIT CHASSIS TO REPAIR FRONT L/H CHASSIS	New	2,800.00	500.00
Gross Labour Cost (S\$)			9,125.00	2,605.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >