



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF23005386/Rqp3e2
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1		Date:	01/08/2023
HEMMANT ROAD SINGAPORE 438675			
ATTN: ENG CUI FEN		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	TP 350T	Veh. Inspected	SKR 7575L
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2023/033	Excess (\$)	0.00
Assign From	ENG CUI FEN	Assign Date	26/05/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA LEXUS IS300 A EXE	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	JTHBA1D2605109832	Colour	GREY
Odometer	53339 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	255/35Z R19	MICHELIN	6 mm
L/H Front Tyre	255/35Z R19	MICHELIN	6 mm
R/H Rear Tyre	255/35Z R19	MICHELIN	6 mm
L/H Rear Tyre	255/35Z R19	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/05/2023	Inspection Date	14/06/2023
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	