6/6/23, 3:37 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG23005423/KNY3M4

Date: 06/06/2023

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001327073

Claimant Vehicle

No: SMX3521M Insured Vehicle No: SLL1320P

Date of Loss: 19/05/2023 Nature of Claim: TP Claim No: 315853

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMX3521M

Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A) Engine No: 3A92UJY5856

Reg. Date: 08/01/2021 (Man. Year: 2020) Chassis No: MMBSTA13AMH003568

Colour: Metallic Black Odometer: 191375 km

Engine Capacity: 1193 cc
Market Value/New Car

Market Value/New Car
Price:
N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55R15 Rear Tyre Size: 185/55R15
Front Left Side: Roadstone 7 mm Rear Left Side: Roadstone 7 mm
Front Right Side: Roadstone 7 mm
Rear Right Side: Roadstone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,221.30	2,950.50	1,270.80	30.10
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,935.00	870.00	1,065.00	55.04
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	6,156.30	3,820.50	2,335.80	37.94
	Approved Total (Overridden) (S\$)		3,000.00		
	Nett Amount (S\$)	6,156.30	3,000.00	3,156.30	51.27

INSPECTION

Date of Assignment: 30/05/2023

LIAN HER MOTORS

Date Inspected: 30/05/2023 Inspected At: BLK 5034, #01-337, ANG MO KIO IND PARK 2

SINGAPORE 569537

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

6/6/23, 3:37 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 06 Jun 2023)

Parts: N/A MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMX3521M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

1		*FRONT O/S HEADLAMP ASSY	Cut	1,299.00 FL	*1,208.00 FL
1		*FRONT SUPPORT PANEL AIR GARNISH	Serviceable	155.00 FL	*- FL
1		*FRONT GRILLE	Serviceable	555.00 FL	*- FL
1		*FRONT GRILLE EMBLEM	Serviceable	55.00 FL	*- FL
1		*FRONT GRILLE TOP GARNISH	Serviceable	155.00 FL	*- FL
1		*FRONT NO PLATE GARNISH	Serviceable	195.00 FL	*- FL
1		*FRONT BUMPER	Cracked	703.00 FL	*703.00 FL
1		*FRONT BUMPER REINFORCEMENT	Bent	466.00 FL	*345.00 FL
1		*FRONT BUMPER LOWER GRILLE	Distorted	155.00 FL	*155.00 FL
1		*FRONT O/S BUMPER SIDE RETAINER	Distorted	55.00 FL	*55.00 FL
1		*FRONT O/S BUMPER CHROME MOULDING - UPPER	Cracked	105.00 FL	*105.00 FL
1		*FRONT O/S BUMPER CHROME MOULDING - LOWER	Cracked	205.00 FL	*205.00 FL
1		*FRONT O/S BUMPER FOG LAMP ASSY	Mtg Cracked	279.00 FL	*279.00 FL
1		*FRONT O/S BUMPER FOG LAMP GARNISH	Dented	85.00 FL	*85.00 FL
1		*FRONT WINDSCREEN WASHER TANK MOTOR	Serviceable	85.00 FL	*- FL
1		*FRONT WINDSCREEN WASHER TANK	Dented	105.00 FL	*105.00 FL
15		*CLIP	Necessary	30.00 FS	*30.00 FS
ınchise	part. S=Spcl	Nett. L=ListItemDisc.	-		
			Sub Total (S\$)	4,687.00	3,275.00
		- List Item Discount on L Items 1	0.00/10.00% (S\$)	465.70	324.50
			Total Parts (S\$)	4,221.30	2,950.50
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 *FRONT GRILLE 1 *FRONT GRILLE EMBLEM 1 *FRONT GRILLE TOP GARNISH 1 *FRONT NO PLATE GARNISH 1 *FRONT BUMPER 1 *FRONT BUMPER REINFORCEMENT 1 *FRONT BUMPER LOWER GRILLE 1 *FRONT O/S BUMPER SIDE RETAINER 1 *FRONT O/S BUMPER CHROME MOULDING - UPPER 1 *FRONT O/S BUMPER CHROME MOULDING - LOWER 1 *FRONT O/S BUMPER FOG LAMP ASSY 1 *FRONT O/S BUMPER FOG LAMP GARNISH 1 *FRONT WINDSCREEN WASHER TANK MOTOR 1 *FRONT WINDSCREEN WASHER TANK 15 *CLIP Inchise part. S=SpcNett. L=ListItemDisc.	1 *FRONT GRILLE EMBLEM Serviceable 1 *FRONT GRILLE TOP GARNISH Serviceable 1 *FRONT NO PLATE GARNISH Serviceable 1 *FRONT BUMPER Cracked 1 *FRONT BUMPER REINFORCEMENT Bent 1 *FRONT BUMPER LOWER GRILLE Distorted 1 *FRONT O/S BUMPER SIDE RETAINER Distorted 1 *FRONT O/S BUMPER CHROME MOULDING - UPPER Cracked 1 *FRONT O/S BUMPER CHROME MOULDING - LOWER Cracked 1 *FRONT O/S BUMPER FOG LAMP ASSY Mtg Cracked 1 *FRONT O/S BUMPER FOG LAMP GARNISH Dented 1 *FRONT O/S BUMPER FOG LAMP GARNISH Dented 1 *FRONT WINDSCREEN WASHER TANK MOTOR Serviceable 1 *FRONT WINDSCREEN WASHER TANK MOTOR Serviceable 1 *FRONT WINDSCREEN WASHER TANK Dented 1 *FRONT WINDSCREEN WASHER TANK DENTE DE	*FRONT GRILLE

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING	New	900.00	400.00
2	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION	New	900.00	450.00
3	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	New	100.00	0.00
4	CHECK AND RECONNECT WIRING	New	35.00	20.00
	Gross Lal	oour Cost (S\$)	1,935.00	870.00
	Report was unsubmitted during t	his print-out		

< END OF ESTIMATES >