

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23005424/UNP3Q2**Date:** 13/06/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00258692202
Claimant Vehicle No :	YP3943D	Insured Vehicle No :	SLC8809Z
Date of Loss:	26/05/2023	Nature of Claim: TP	Claim No: SNM23D203778/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP3943D		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER4SDEB (CBU) (M)	Engine No:	4P10C26040
Reg. Date:	30/08/2016 (Man. Year: 2016)	Chassis No:	FEB21EA20892
Colour:	White	Odometer:	192212 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85 R15	Rear Tyre Size:	195/85 R15 (D)
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6/6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,574.32	5,891.96	23,682.36	80.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,850.00	1,900.00	7,950.00	80.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	39,424.32	7,791.96	31,632.36	80.24
Approved Total (Overridden) (S\$)		6,200.00		
(S\$)	39,424.32	6,200.00	33,224.32	84.27
+ GST 8.00/8.00% (S\$)	3,153.95	496.00	2,657.95	84.27
Nett Amount (S\$)	42,578.27	6,696.00	35,882.27	84.27

INSPECTION

Date of Assignment:	29/05/2023	
Date Inspected:	30/05/2023	Inspected At: 1 KAKI BUKIT AVE 6 #01-73, AUTOBAY @KAKI BUKIT SINGAPORE 417883 Repairer:SPEEDWERKZ PTE LTD (HQ)
Estimated Period of Repair:	6.0 days	

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 13 Jun 2023)	
Parts:	N/A	mitsubishi canter 3.0 d feb21er4sdeb (cbu) (m) (model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP3943D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	1,485.00 FL	*1,133.01 FL
2	2		*FRONT BUMPER SIDE RUBBER (N/S TORN)	Not Consistent With The Impact	494.00 FL	*- FL
3	2		*FRONT BUMPER BRACKET	Not Necessary	392.60 FL	*- FL
4	1		*FRONT GRILLE	Not Necessary	1,756.00 FL	*- FL
5	1		*FRONT LOGO	Not Necessary	158.00 FL	*- FL
6	1		*FRONT GRILLE CENTRE BRACKET	Not Necessary	147.00 FL	*- FL
7	1		*FRONT FUSO EMBLEM	Not Necessary	284.00 FL	*- FL
8	1		*FRONT PANEL	Not Necessary	2,320.00 FL	*- FL
9	2		*FRONT WIPER NOZZLE	Not Necessary	79.80 FL	*- FL
10	1		*FRONT WIPER LINKAGE	Not Necessary	567.00 FL	*- FL
11	1		*FRONT WIPER MOTOR	Not Necessary	583.50 FL	*- FL
12	1		*FRONT WIPER PANEL	Not Necessary	355.20 FL	*- FL
13	1		*HEAD LAMP	O/S Not Necessary / N/SCracked	1,970.00 FL	*856.30 FL
14	1		*SIDE LAMP	O/S Not Necessary / N/SCracked	518.40 FL	*161.10 FL
15	2		*SIGNAL LAMP	Not Necessary	648.60 FL	*- FL
16	2		*FRONT CORNER PANEL	Not Necessary	1,310.00 FL	*- FL
17	1		*AIRCOND BLOWER & COOLING COIL UNIT	Not Necessary	3,120.00 FL	*- FL
18	1		*TAIL LAMP (N/S CRACKED) (N/S CONSISTENT WITH THE IMPACT)	O/S Cracked	650.00 FL	*244.10 FL
19	1		*REAR NUMBER PLATE	Bent	86.25 FS	*15.00 FS
20	1		*REAR NUMBER PLATE BASE	Bent	185.00 FL	*108.10 FL
21	1		*REAR CARRIER WOODEN CHASSIS BEAM	N/S Not Necessary /O/S Cracked	3,000.00 FS	*1,500.00 FS
22	1		*REAR CARRIER FLOOR WOODEN PANEL	Not Necessary	4,800.00 FS	*- FS
23	1		*REAR SAFETY BAR W/BACKET	Distorted	2,500.00 FS	*1,200.00 FS
24	8		*REAR CARRIER & BOLT	Not Necessary	880.00 FS	*- FS
25	1		*REAR CARRIER WOODEN TAIL GATE	Not Necessary	1,800.00 FS	*- FS
26	4		*REAR CARRIER WOODEN TAIL GATE HINGE BRACKET	Not Necessary	1,000.00 FS	*- FS
27	1		*REAR CARRIER TAIL GATE SUPPORT BEAM (LOWER)	Cracked	1,500.00 FS	*900.00 FS
28	1		*REAR CARRIER CROSS STEP WOODEN BEAM	Broken	850.00 FS	*400.00 FS
29	1		*REAR NUMBER PLATE	Repeated	45.00 FS	*- FS
30	1		*FRONT NUMBER PLATE	Not Necessary	45.00 FS	*- FS
31	1		*REMOVE AND REFIX FRONT WINDSCREEN GLASS	Not Necessary	250.00 FS	*- FS
32	1		*70 K/M STICKER	Not Necessary	25.00 FS	*- FS
33	1		*23 PAX STICKER	Not Necessary	25.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	33,830.3
------------------	----------

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR CARRIER TO ASSIST REPAIR CHASSIS	New	650.00	300.00
2	REMOVE AND REFIX METER DASHBOARD AND WIRING	New	550.00	0.00
3	REMOVE AND REFIX AIRCOND BLOWER ,HEATER UNIT REFILL GAS ETC	New	350.00	0.00
4	LABOUR CHARGES STRAIGHTEN FRONT AND REAR CHASSIS KNOCK OUT DENTS ON DAMAGE PORTION ,CUT AND WELDING RENEW PARTS	New	5,500.00	1,000.00
5	RESPRAY PAINTING	New	2,800.00	600.00
Gross Labour Cost (\$\$)			9,850.00	1,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >