



# ABSOLUTE APPRAISAL SERVICES PTE LTD

## Loss Adjusters & Motor Appraisers

160 Sin Ming Drive, #05-11 Sin Ming AutoCity (S) 575 722

Email: absolute.app.svcs@gmail.com Mobile: 9688 0413

### Vehicle Inspection Report

To: Kee Gek Kwee  
C/o: 5 Soon Lee Street #01-34 Pioneer Point  
Singapore 627607

Report No: AAS/2023/012

Date of report: 14.03.2023  
Date of request: 03.02.2023  
Date of inspection: 03.02.2023  
Date of accident: 01.02.2023  
Claim type: Third Party Claim

### Particulars of affected vehicle:

Registration no: SNG1169M  
Make/Model: Toyota Voxy (A)  
Year of registration: 2008/09  
Colour: Metallic Black

Odometer: 258307 km  
Engine Capacity: 1986 cc  
Engine no: 3ZR4200638  
Chassis no: ZRR700147403

### Condition of tires:

Front Left: 6mm  
Make: Yokohama

Rear Left: 6mm  
Make: Yokohama

Front Right: 6mm  
Make: Yokohama

Rear Right: 6mm  
Make: Yokohama

Type of road wheel: Alloy (The above represent the remaining life of the tire thread)

### Pre-accident condition (Static tests only)

General Bodywork : Good  
Paintwork : Good  
Handbrake : In order  
Footbrake : In order  
Steering : In order  
Apparent engine modification : Nil

### The Assignment

The inspection was conducted at M/s. SK Garage Motorsports  
5 Soon Lee Street #01-34 Pioneer Point  
Singapore 627607

(Subsequent inspection was conducted)

### Assessment

Repairer's estimate: \$ 8,406.95

Revised estimate: \$ 7,087.50

Recommended reserve: \$ 5,650.00 (Lump sum)

Estimated normal duration of repairs : 6 Working days



# ABSOLUTE APPRAISAL SERVICES PTE LTD

## Loss Adjusters & Motor Appraisers

160 Sin Ming Drive, #05-11 Sin Ming AutoCity (S) 575 722

Email: absolute.app.svcs@gmail.com Mobile: 9688 0413

Vehicle No: SNG1169M

Report No: AAS/2023/012

### W/O PREJUDICE

#### Point of impact

At the RHR portion.

#### General description of damages

The tailgate, tailgate glass, tail lamp LH, rear bumper, roof panel, etc.

Other parts were also found damaged. (See schedule for details)

#### Recommendation

The estimate cost of repair submitted by M/s SK Garage Motorsports as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$7,087.50

#### Conclusion

The repairer has agreed to undertake the repair at a lumpsum of SGD \$5,650.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 6 working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a '**Without Prejudice**' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 76 photographs.

Your Faithfully  
Absolute Appraisal Services Pte Ltd



Nicky Sean  
Automobile Appraiser  
MSAAA / MSMCTA



# ABSOLUTE APPRAISAL SERVICES PTE LTD

## Loss Adjusters & Motor Appraisers

160 Sin Ming Drive, #05-11 Sin Ming AutoCity (S) 575 722

Email: absolute.app.svcs@gmail.com Mobile: 9688 0413

Vehicle No: SNG1169M

Report No: AAS/2023/012

### Appraisal Schedule

S/N	Parts Description	Qty	Condition		Repairer's Est	Revised Est
1	Tailgate	1	Dented		\$ 1,860.10	\$ 1,860.10 ✓
2	Tailgate glass	1	Shattered		\$ 1,462.30	\$ 1,462.30 ✓
3	Tailgate glass side moulding	2	Necessary	\$ 59.70	\$ 119.40	\$ 119.40 ✓
4	Tailgate glass lower moulding	1	Necessary	\$ 71.30	\$ 71.30	\$ 71.30 ✓
5	Tailgate glass spacer LH/RH	2	Necessary	\$ 15.90	\$ 31.80	\$ 31.80 ✓
6	Tailgate glass centre trim	1	Refit		\$ 197.10	- X nn
7	Tailgate glass side trim LH/RH	2	LH Cut	\$ 159.50	\$ 319.00	\$ 159.50 ✓
8	Tailgate emblem	1	Necessary		\$ 112.00	\$ 112.00 ✓
9	Tailgate spoiler	1	Cracked		\$ 1,185.10	\$ 1,185.10 ✓
10	Tailgate third brake light	1	Broken		\$ 322.30	\$ 322.30 ✓
11	Tailgate hinge LH/RH	2	Distorted	\$ 87.90	\$ 175.80	\$ 175.80 ✓
12	Tailgate lifter LH/RH	2	Bent/Leaked	\$ 159.40	\$ 318.80	\$ 318.80 ✓
13	Tailgate inner trim	1	Refit		\$ 896.00	- X nn
14	Tail lamp LH	1	Broken	Not consistent - NC	\$ 951.60	\$ 951.60 X
15	Roof panel		Dented/Repair		-	- X R
16	Rear bumper		Grazed/Repair	Not consistent - NC	-	- X
				<b>5818.40</b>		
				<b>-25%</b>	Total:	\$ 8,022.60
				<b>4363.80</b>	-25%	\$ 2,005.65
					List total:	\$ 6,016.95
						\$ 5,077.50
1	Tailgate glass sealant	1	Necessary		\$ 60.00	\$ 40.00 ✓
2	Tailgate inner trim clips	1set	Necessary		\$ 50.00	20 ✓ \$ 30.00
3	Tailgate glass solar film	1	Necessary		\$ 300.00	150 ✓ \$ 250.00
				<b>210</b>	Special nett total:	\$ 410.00
						\$ 320.00
					Parts Total:	\$ 6,426.95
						\$ 5,397.50



# ABSOLUTE APPRAISAL SERVICES PTE LTD

## Loss Adjusters & Motor Appraisers

160 Sin Ming Drive, #05-11 Sin Ming AutoCity (S) 575 722

Email: absolute.app.svcs@gmail.com Mobile: 9688 0413

Vehicle No: SNG1169M

Report No: AAS/2023/012

S/N Labour Description

Repairer's Est Revised Est

1	Remove & transfer tailgate component.		\$ 120.00	50	\$ 100.00
2	Remove & transfer reverse camera.		\$ 80.00	30	\$ 50.00
3	Remove roof lining to make way for repair.		\$ 250.00	100	\$ 220.00
4	Spray painting on rear affected & replacement panels.		\$ 800.00	500	\$ 750.00
5	Conduct panel beating, straightening & reforming. Renew rear damaged parts. Re-align all affected area.		\$ 600.00	400	\$ 500.00
6	Check lightings & wirings.		\$ 50.00		\$ 30.00 ✓
7	Anti rust on affected panels.	1150	\$ 80.00		\$ 40.00 ✓

Labour Total:	\$ 1,980.00	\$ 1,690.00
---------------	-------------	-------------

Grand Total:	\$ 8,406.95	\$ 7,087.50
--------------	-------------	-------------

The final adjusted lump sum amount is \$5,650.00

5723.80

Under normal circumstances, the repair should be completed within a reasonable period of 6 working days.

L/S - 4579.04  
= 4600

76 Photographs were taken at the time of inspection.

4 days