



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 7681X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	HANDLE	BENT	435.50	435.50
1	SET HANDLE GUARD	GRAZED	235.50	235.50
1	HANDLE BALANCER	GRAZED	85.90	85.90
1	SET MIRROR	NOT NECESSARY	275.90	-
1	FRONT RIGHT LOWER FARRING	GRAZED	535.90	535.90
1	FRONT RIGHT LOWER INNER FARRING	GRAZED	475.50	475.50
1	GLIDER FRAME SLIDER RH	GRAZED	350.00	170.00
1	FRONT LOWER COVER	NOT NECESSARY	425.00	-
1	FRONT PEDAL ASSEMBLY WITH BRACKET	NOT NECESSARY	625.00	-
1	EXHAUST SIDE COVER PROTECTOR	NOT NECESSARY	275.10	-
1	REAR RIGHT SIGNAL	CUT	170.00	170.00
1	REAR NUMBER PLATE	BENT	40.00	40.00
1	REAR TAIL FENDER	NOT NECESSARY	335.00	-
	LESS 10% DISCOUNT		-426.43	-214.83
			3,837.87	1,933.47
SPECIAL NETT ITEMS				
1	RIGHT CARRIER BOX (RED) (SN)	GRAZED	1,335.00	500.00
1	RIGHT CARRIER BRACKET (SN)	BENT	375.00	220.00
			1,710.00	720.00
LABOUR				
	REFIX, REMOVE, REPLACE OF AFFECTED PARTS.		900.00	300.00
	SPRAY PAINT AT AFFECTED PORTION.		700.00	400.00
			1,600.00	700.00
GRAND TOTAL			7,147.87	3,353.47
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,700.00

Report Ref No. CS3/SMR21009820/Dny3e2-1

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.