

Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point
Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	WDD1173422N709888	Date of Loss:	19/05/2023
Vehicle Reg. No.:	SME7631C	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	YIP YING EE	Contact No:	+6590928330
Make/Model:	MERCEDES-BENZ C180, 1.6 (A)	Vehicle Reg. Date:	16/10/2018
Vehicle Colour:	GREY	Chassis No:	WDD1173422N709888
Engine No:	27091031721331		
Odometer:	55882 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	ACCORD AUTO SERVICES PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	2,959.00
Miscellaneous Items	105.00
Labour	980.00
Paintwork Labour	300.00
Towing	0.00
Gross Total (S\$)	4,344.00
+ GST 8.00% (S\$)	347.52
Nett Amount (S\$)	4,691.52

This claim is handled by: **LAI YEAN KUAN**Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 May 2023)

Parts: 143 MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: **Accord Auto Services Pte Ltd/SME7631C/27/05/2023 20:01**

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER <i>de /</i>	0.00	0.00	*880.00 F
2	1		*FRONT BUMPER GRILLE ASSY ?	0.00	0.00	*1,200.00 F
3	1		*FRONT BUMPER EMBLEM <i>sun /</i>	0.00	0.00	*90.00 F
4	1		*FRONT BUMPER LOWER GRILLE ?	0.00	0.00	*200.00 F
5	1		*FRONT BUMPER TOW COVER <i>MIS /</i>	0.00	0.00	*45.00 F
6	1		*FRONT BUMPER LOWER CENTER CHROME MOULDING <i>MIS /</i>	0.00	0.00	*180.00 F
7	1		*FRONT BUMPER NUMBER PLATE GARNISH <i>de /</i>	0.00	0.00	*95.00 F

F=Franchise part.

Sub Total (S\$)	2,690.00
+ Margin on L,N Items 10.00% (S\$)	269.00
Total Parts (S\$)	2,959.00

Accord Auto Services Pte Ltd/SME7631C/27/05/2023 20:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	CAR PLATE NUMBER WITH FRAME <i>51</i>	45.00
2	1	NECESSARY CLIPS <i>na</i>	60.00
Sub Total (S\$)			105.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	Spray Painting to All Affected Areas	New	<i>250</i> 300.00
Labour Items			
2	Labour Remove / Refix Accident Damages parts to knock , jack, cut weld and realign accident affected area	New	<i>300</i> 600.00
3	Check Wiring System & Light	New	<i>40</i> 80.00
4	Computer Diagnostic (Reset Necessary Electronic Function)	New	<i>200</i> 300.00
Gross Labour Cost (S\$)			1,280.00

Accord Auto Services Pte Ltd/SME7631C/27/05/2023 20:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasm
Hp 900/10068
3 days
4s
EXCESS: TBA
31/05/23 101120
Rever
Res after spray