

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III23005431/KVY3E2**Date:** 15/06/2023**REFERENCE**

Insured/Claimant: COMFORTDELGRO RENT-A-CAR PTE LTD Policy No: D20MFL0000326_02

Date of Loss: 13/05/2023

Nature of Claim: OD

Claim No: MFL2022D0002517

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMW3320G**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 Elegance 2WD (A) Engine No: 1ZR0F49017
 Reg. Date: 16/11/2020 (Man. Year: 2020) Chassis No: MR2BE3BE000010153
 Colour: Metallic Pearl White Odometer: 18051 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: S\$109,000.00
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
 Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 8 mm
 Front Right Side: Dunlop 8 mm Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,661.25	1,242.75	3,418.50	73.34
Miscellaneous Items	46.00	46.00	0.00	0.00
Labour	1,250.00	860.00	390.00	31.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,957.25	2,148.75	3,808.50	63.93
- Excess (S\$)	0.00	1,750.00	-1,750.00	
(S\$)	5,957.25	398.75	5,558.50	93.31
+ GST 8.00/8.00% (S\$)	476.58	31.90	444.68	93.31
Nett Amount (S\$)	6,433.83	430.65	6,003.18	93.31

INSPECTION

Date of Assignment: 29/05/2023 Present Location: ComfortDelGro Engineering Pte Ltd (Braddell)
 Date Inspected: 29/05/2023 Inspected At: ComfortDelGro Engineering Pte Ltd (Braddell)
 205 Braddell Road
 Singapore 579701
 Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jun 2023)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 Elegance 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW3320G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	512.00 FL	*512.00 FL
2	1		*FRONT RADIATOR GRILLE	Dented	246.00 FL	*246.00 FL
3	1		*FRONT BUMPER LOWER GRILLE	Cracked	431.00 FL	*431.00 FL
4	1		*FRONT BUMPER LOWER GRILLE BASE	Serviceable	398.00 FL	*- FL
5	1		*FRONT BUMPER SPONGE	Serviceable	88.00 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	Repair	432.00 FL	*- FL
7	1		*RH HEADLAMP	Serviceable	1,820.00 FL	*- FL
8	1		*LH HEADLAMP	Serviceable	1,820.00 FL	*- FL
Supplementary #1						
9	1		*FRONT BUMPER	Cracked	468.00 FL	*468.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)					6,215.00	1,657.00
- List Item Discount on L Items 25.00/25.00% (\$\$)					1,553.75	414.25
Total Parts (\$\$)					4,661.25	1,242.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<u>Supplementary #1</u>				
2	1	FRONT NUMBER PLATE (DENTED)	35.00	35.00
Sub Total (S\$)			46.00	46.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	To knock & straighten on accident area, to remove & refit Front damage parts.	New	600.00	400.00
2	To putty & respray on Front damage area.	New	600.00	440.00
3	To check wiring & focus headlamp.	New	50.00	20.00
Gross Labour Cost (S\$)			1,250.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >