

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT       |   |   |                  |       |                         |  |
|------------------------------------|---|---|------------------|-------|-------------------------|--|
|                                    | HSBC LIFE (SING   | APORE) PTE LTD  |                  | Ref:  | CS3/HSB23005450/Tvp3m4  |  |
|                                    |   | EVARD #48-01 MARINA BAY<br>RE TOWER 2 SINGAPORE                 |                  | Date: | 06/06/2023              |  |
|                                    | ATTN: KHOR SAW  | THENG   |                  | Code: | HSB                     |  |
| 1.                                 | 1. Policy Particulars :- (THIRD PARTY CLAIM)  |   |                  |       |                         |  |
|                                    | Insured Veh.  | SHD 4692K   | Veh. Inspected   |       | SMJ 2990Y               |  |
|                                    | Policy No.  |   | Coverage (\$)    |       | 0.00                    |  |
|                                    | Claim No.   | S3M04MW9  | Excess (\$)      |       | 0.00                    |  |
|                                    | Assign From   | KHOR SAW THENG  | Assign Date      |       | 29/05/2023              |  |
| 2. Vehicle Particulars & Condition |   |   |                  |       |                         |  |
|                                    | Make & Model  | HONDA FREED HYBRID  | c.c              |       | 1496                    |  |
|                                    | Engine No.  | HIDDEN  | Year of Reg.     |       | 2019                    |  |
|                                    | Chassis No.   | GB71084064  | Colour           |       | BLUE                    |  |
|                                    | Odometer  | 319269 KM   | Steering         |       | IN ORDER                |  |
|                                    | Brakes  | IN ORDER  | Modification     |       | SPORTS RIM              |  |
|                                    | General   | GOOD  |                  |       |                         |  |
| 3. Conditions of Tyres             |   |   |                  |       |                         |  |
|                                    |   | Size  | Make             |       | Balance                 |  |
|                                    | R/H Front Tyre  | 185/65R15   | DUNLOP           |       | 6 mm                    |  |
|                                    | L/H Front Tyre  | 185/65R15   | DUNLOP           |       | 6 mm                    |  |
|                                    | R/H Rear Tyre   | 185/65R15   | DUNLOP           |       | 6 mm                    |  |
|                                    | L/H Rear Tyre   | 185/65R15   | DUNLOP           |       | 6 mm                    |  |
| 4. Description of Damages          |   |   |                  |       |                         |  |
|                                    | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  |   |                  |       |                         |  |
| 5.                                 | 5. General Information  |   |                  |       |                         |  |
|                                    | Accident Date   | 27/05/2023  | Inspect Date / T | Γime  | 30/05/2023 ( 03:32 PM ) |  |
|                                    | Survey held at  | APEX MOTORING   |                  |       |                         |  |
|                                    |   | 25 KAKI BUKIT ROAD 4<br>#01-55 SYNERGY @ KB<br>SINGPORE 417800. |                  |       |                         |  |
| 5a.                                | Remarks   |   |                  |       |                         |  |
|                                    | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000 |   |                  |       |                         |  |
| 5b.                                | Estimate Days of Repair   |   |                  |       |                         |  |
|                                    | STIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days   |   |                  |       |                         |  |
|                                    |   | Poport Pof No. CS2/L  | 1000000000       | 2 4   |                         |  |

Report Ref No. CS3/HSB23005450/Tvp3m4

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.