

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

HSBC LIFE (SINGAPORE) PTE LTD   Ref: CS3/HSB23005465/D     10 MARINA BOULEVARD   Date: 28/07/2023     #48-01 MARINA BAY FINANCIAL CENTRE TOWER     2SINGAPORE 018983   ATTN: TEO KITTY   Code: HSB     1.	np3e2	
#48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: TEO KITTY  Code: HSB  1. Policy Particulars:- (THIRD PARTY CLAIM)  Insured Veh. SH 6307J  Veh. Inspected SKE 163G  Policy No. VFX/P2419138  Coverage (\$) 0.00  Claim No. S3M04MWH  Excess (\$) 0.00		
Policy Particulars :- (THIRD PARTY CLAIM)           Insured Veh.         SH 6307J         Veh. Inspected         SKE 163G           Policy No.         VFX/P2419138         Coverage (\$)         0.00           Claim No.         S3M04MWH         Excess (\$)         0.00		
Insured Veh. SH 6307J   Veh. Inspected   SKE 163G		
Policy No.         VFX/P2419138         Coverage (\$)         0.00           Claim No.         S3M04MWH         Excess (\$)         0.00	1. Policy Particulars :- (THIRD PARTY CLAIM)	
Claim No. S3M04MWH Excess (\$) 0.00		
W,		
Assign From TEO KITTY Assign Date 30/05/2023		
1		
2. Vehicle Particulars & Condition		
Make & Model NISSAN X-TRAIL c.c 1997		
Engine No. HIDDEN Year of Reg. 2016		
Chassis No. JN1JANT32Z0001812 Colour SILVER		
Odometer 111061 KM Steering IN ORDER		
Brakes IN ORDER Modification SPORTS RIM		
General GOOD		
3. Conditions of Tyres		
Size Make Balance		
R/H Front Tyre         235/60 R18         MICHELIN         5 mm		
L/H Front Tyre 235/60 R18 MICHELIN 5 mm		
R/H Rear Tyre 235/60 R18 MICHELIN 5 mm		
L/H Rear Tyre 235/60 R18 MICHELIN 5 mm		
4. Description of Damages		
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.		
5. General Information		
Accident Date 28/05/2023 Inspect Date / Time 06/06/2023 ( 03:00 PM	1)	
Survey held at SIN SENG HONG SPRAY PAINTING & SERVICES		
3023A UBI ROAD 1 #01-63 SINGAPORE 408717		
5a. Remarks		
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$400-\$500		
5b. Estimate Days of Repair		
ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days		

Report Ref No. CS3/HSB23005465/Dnp3e2

Inspected By

ANG BRYAN TANI

K.K.LAU CPT(RET)

Automotive Assessor / Investigator

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser