

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

HL Assurance Pte Ltd
11 Keppel Road, #11-01 ABI Plaza
Singapore 089057

Our File No: CS/HLA23005466/KNY3Q2**Date:** 03/08/2023**REFERENCE**

Insured/Claimant:	LAM HIN CHEW	Policy No:	MP314066	
Date of Loss:	25/05/2023	Nature of Claim:	OD	Claim No: MPC04287

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS1682H	Engine No:	3ZRB769810
Make & Model:	TOYOTA HARRIER, 2.0 (A)	Chassis No:	ZSU600076537
Reg. Date:	24/08/2017 (Man. Year: 2016)	Odometer:	118856 km
Colour:	Metallic Black		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	S\$89,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,942.25	5,102.15	1,840.10	26.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	1,820.00	1,030.00	36.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,792.25	6,922.15	2,870.10	29.31
- Excess (S\$)	0.00	375.00	-375.00	
(S\$)	9,792.25	6,547.15	3,245.10	33.14
+ GST 8.00/8.00% (S\$)	783.38	523.77	259.61	33.14
Nett Amount (S\$)	10,575.63	7,070.92	3,504.71	33.14

INSPECTION

Date of Assignment:	30/05/2023	Present Location:	Ah Lim Motor Company (Sin Ming)
Date Inspected:	05/06/2023	Inspected At:	Ah Lim Motor Company (Sin Ming) 176 Sin Ming Drive #05-12, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	6.0 days		

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Aug 2023)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS1682H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Buckled	450.00 F	*450.00 F
2	1		*FRONT BONNET CHROME MOULDING	Cracked	105.00 F	*105.00 F
3	2		*HEADLAMP LH/RH	Mtg Cracked	1,800.00 F	*1,800.00 F
4	1		*RADIATOR GRILLE	Cracked	200.00 F	*200.00 F
5	1		*FRONT BUMPER	Buckled / Cracked	250.00 F	*250.00 F
6	2		*FRONT BUMPER SIDE RETAINER LH/RH	Distorted	90.00 F	*90.00 F
7	15		*FRONT BUMPER CLIP	Necessary	22.50 F	*22.50 F
8	1		*FRONT BUMPER REINFORCEMENT	Bent	160.00 F	*160.00 F
9	1		*FRONT BUMPER SPONGE	Cracked	45.00 F	*45.00 F
10	1		*FRONT BUMPER BEAM CENTRE	Bent	100.00 F	*100.00 F
11	2		*FRONT BUMPER BEAM SIDE LH/RH	Repair	96.00 F	*- F
12	1		*FRONT BUMPER LOWER GRILLE	Distorted	105.00 F	*105.00 F
13	2		*FRONT BUMPER TOWING COVER LH/RH	Serviceable	30.00 F	*- F
14	1		*FRONT BUMPER LOWER GARNISH	Serviceable	120.00 F	*- F
15	1		*FRONT BUMPER UNDER TRAY	Serviceable	75.00 F	*- F
16	2		*FRONT BUMPER SPONGE SIDE LH/RH	Serviceable	50.00 F	*- F
17	2		*FRONT FENDER LH/RH	Buckled	530.00 F	*530.00 F
18	1		*FRONT BONNET LOCK	Distorted	65.00 F	*65.00 F
19	1		*RADIATOR SUPPORT PANEL	Repair	320.00 F	*- F
20	1		*BRACE PANEL	Bent	95.00 F	*95.00 F
21	16		*FENDER COWLING CLIP	Necessary	24.00 F	*24.00 F
22	1		*SUPPORT PANEL TOP COVER	Serviceable	140.00 F	*- F
23	10		*SUPPORT PANEL TOP COVER CLIP	Necessary	15.00 F	*15.00 F
24	2		*RADIATOR SIDE AIR GUIDE UPPER OUTER LH/RH	Serviceable	120.00 F	*- F
25	2		*RADIATOR SIDE AIR GUIDE INNER LH/RH	Serviceable	110.00 F	*- F
26	1		*AIR CON CONDENSER	Bent	550.00 F	*550.00 F
27	1		*RADIATOR	Serviceable	580.00 F	*- F
28	1		*RADIATOR COOLANT	Not Necessary	35.00 FS	*- FS
29	1		*FRONT NO PLATE	Bent	35.00 FS	*35.00 FS
						F=Franchise part. S=SpcNett.
					Sub Total (S\$)	6,317.50 4,641.50
					+ Margin on L,N Items 10.00/10.00% (S\$)	624.75 460.65
					Total Parts (S\$)	6,942.25 5,102.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND REFOCUS HEADLAMP	New	30.00	20.00
2	TO DISMANTLE AND REFIT AIRCON CONDENSER AND REFILL WITH AIR CON GAS	New	120.00	100.00
3	TO DISMANTLE AND REPLACE DAMAGE PARTS TO CUT; KNOCK AND WELD FRON SUPPORT PANEL KNOCK; ALIGN AND REPAIR FRONT AFFECTED AREA	New	1,100.00	700.00
4	TO SPRAY BONNET INNER / OUTER; FRONT FENDER LH; FRONT FENDER RH; FRONT BUMPER; FRONT DOOR LH; FRONT DOOR RH AND FRONT SUPPORT PANEL	New	1,600.00	1,000.00
Gross Labour Cost (\$\$)			2,850.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >