

AH LIM MOTOR COMPANY

176 SIN MING DRIVE #05-12
SIN MING AUTOCARE Singapore 575721
Tel: 64563637 Fax: Email:
GST Reg No: M9-0009639-E

SURVEYOR COPY

INSURER: HL Assurance Pte Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/HL
Policy No:	MP314066	Date of Loss:	25/05/2023
Vehicle Reg. No.:	SLS1682H	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LAM HIN CHEW	Contact No:	+6582009361
Driver:	LAM HIN CHEW		

Make/Model:	TOYOTA HARRIER, 2.0 (A)	Vehicle Reg. Date:	24/08/2017
Vehicle Colour:	BLACK	Chassis No:	ZSU600076537
Engine No:	3ZRB769810		
Odometer:	0 KM		

Paint Type: NO
Total Loss? NO
Est. Duration of Repair (day) 86 days

Not with claim
Repair by claim
Ex @ 375h

Remarks: WORKSHOP HANDLER- MEILI TAN TEL: 6456 3637 EMAIL : MEILI@ALMSM.COM.SG VEHICLE IS CURRENTLY NOT IN THE WORKSHOP
Present Location: AH LIM MOTOR COMPANY (SIN MING)

COST OF CLAIMS	Amount
Parts	6,942.25
Miscellaneous Items	0.00
Labour	2,850.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	9,792.25
+ GST 8.00% (\$)	783.38
Nett Amount (\$)	10,575.63

This claim is handled by: MEILI TAN-SIN MING BRANCH

Generated using Merimen e-Claims Internet Estimation & Adjusting System

AH LIM MOTOR COMPANY
(SIN MING BRANCH)
176, Sin Ming Drive, #05-12
Sin Ming Autocare, Singapore 575721
Tel: 6456 3637 Fax: 6456 3686

SURVEYOR COPY

DETAILS

ence

Source: MRM-SG Version: 1.0 (Last Synchronised: 29 May 2023)
 Parts: M1-SUV TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLS1682H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BONNET	Bu 0.00	0.00	*450.00 F	✓
2	1		*FRONT BONNET CHROME MOULDING	CM 0.00	0.00	*105.00 F	✓
3	2		*HEADLAMP LH/RH	my CM 0.00	0.00	*1,800.00 F	✓
4	1		*RADIATOR GRILLE	CM Bu 0.00	0.00	*200.00 F	✓
5	1		*FRONT BUMPER	0.00	0.00	*250.00 F	✓
6	2		*FRONT BUMPER SIDE RETAINER LH/RH	0.00	0.00	*90.00 F	✓
7	15		*FRONT BUMPER CLIP	0.00	0.00	*22.50 F	✓
8	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*160.00 F	✓
9	1		*FRONT BUMPER SPONGE	CM 0.00	0.00	*45.00 F	✓
10	1		*FRONT BUMPER BEAM CENTRE	R 0.00	0.00	*100.00 F	✓
11	2		*FRONT BUMPER BEAM SIDE LH/RH	0.00	0.00	*96.00 F	✓
12	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	*105.00 F	✓
13	2		*FRONT BUMPER TOWING COVER LH/RH	0.00	0.00	*30.00 F	✓
14	1		*FRONT BUMPER LOWER GARNISH	0.00	0.00	*120.00 F	✓
15	1		*FRONT BUMPER UNDER TRAY	0.00	0.00	*75.00 F	✓
16	2		*FRONT BUMPER SPONGE SIDE LH/RH	0.00	0.00	*50.00 F	✓
17	2		*FRONT FENDER LH/RH	Bu 0.00	0.00	*530.00 F	✓
18	1		*FRONT BONNET LOCK	0.00	0.00	*65.00 F	✓
19	1		*RADIATOR SUPPORT PANEL	0.00	0.00	*320.00 F	✓
20	1		*BRACE PANEL	R 0.00	0.00	*95.00 F	✓
21	16		*FENDER COWLING CLIP	0.00	0.00	*24.00 F	✓
22	1		*SUPPORT PANEL TOP COVER	0.00	0.00	*140.00 F	✓
23	10		*SUPPORT PANEL TOP COVER CLIP	0.00	0.00	*15.00 F	✓
24	2		*RADIATOR SIDE AIR GUIDE UPPER OUTER LH/RH	0.00	0.00	*120.00 F	✓
25	2		*RADIATOR SIDE AIR GUIDE INNER LH/RH	0.00	0.00	*110.00 F	✓
26	1		*AIR CON CONDENSER	0.00	0.00	*550.00 F	✓
27	1		*RADIATOR	0.00	0.00	*580.00 F	✓
28	1		*RADIATOR COOLANT	0	0.00	*35.00 FS	✓
29	1		*FRONT NO PLATE	0	0.00	*35.00 FS	✓
Sub Total (\$\$)						6,317.50	
+ Margin on L,N Items 10.00% (\$\$)						624.75	
Total Parts (\$\$)						6,942.25	

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

AH LIM MOTOR COMPANY
 (SIN MING BRANCH)
 176, Sin Ming Drive, #05-12
 Sin Ming Autocare, Singapore 575721
 Tel: 6456 3637 Fax: 6456 3686

Estimate Report

	Items	Lab.Type	Amount
	TO CHECK WIRING AND REFOCUS HEADLAMP	New	30.00
	TO DISMANTLE AND REFIT AIRCON CONDENSER AND REFILL WITH AIR CON GAS	New	120.00
3	TO DISMANTLE AND REPLACE DAMAGE PARTS TO CUT; KNOCK AND WELD FRON SUPPORT PANEL KNOCK; ALIGN AND REPAIR FRONT AFFECTED AREA	New	1,100.00
4	TO SPRAY BONNET INNER / OUTER; FRONT FENDER LH; FRONT FENDER RH; FRONT BUMPER; FRONT DOOR LH; FRONT DOOR RH AND FRONT SUPPORT PANEL	New	1,600.00
Gross Labour Cost (\$\$)			2,850.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

AH LIM MOTOR COMPANY
(SIN MING BRANCH)
176, Sin Ming Drive, #05-12
Sin Ming Autocare, Singapore 575721
Tel: 6456 3637 Fax: 6456 3686

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: