



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## OPINION ON REPAIR COST FOR VEHICLE NO. SNA 5143S

Qty	Description of Parts	Condition	Recommended (\$)
<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	BUCKLED	481.40
1	REAR BUMPER REINFORCEMENT	BENT	294.80
1	REAR BUMPER CLIPS	NECESSARY	50.00
1	REAR BUMPER LOWER GARNISH	DENTED	340.60
1	REAR END PANEL	TO REPAIR SEE LABOUR	-
	LESS 20% DISCOUNT		-233.36
			933.44
<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	200.00
			200.00
<b><u>LABOUR</u></b>			
	LABOUR TO PANEL BEAT THE ABOVE. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		400.00
	LABOUR TO SPRAY PAINT AFFECTED PARTS.		400.00
	CHECK WIRING.		15.00
	REMOVE & REFIT REVERSE SENSOR.		50.00
			865.00
<b>GRAND TOTAL</b>			<b>1,998.44</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>	<b>1,600.00</b>
---	-----------------

Report Ref No. CS3/SPF23005471/Kny3m4

**NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000**

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**