

ASS. REC. BY:

REF:

SPF / 230054711kin

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / QD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s Zeon Auto Pro

of 919C

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$ 61K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SNA 5143S Yr Regn: 10, 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Elantra C.C 1591

Colour: M.P. white AC: Insured / Std / NI / NA

Sp. Reading: 164840 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM11D 841CATU 550387

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD / VRlm or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 10/3/23

Rear

R/Bal. 9 mm

L/Bal. 9 mm

D.O.I. 30/5/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 / PRP, no document given

04 repair cost \$2-3K

07/06/23 Submit DAR - LS \$1600, 4 days. Cost range of COR = \$100 - \$2000

Date/Time, File Pass to?

07/06/2023

1) Typist

Date/Time, File Return to?

2)

: Prell. Report

: Final Report

Days Of Repair: 04

Resurvey No. of Trip: _____

Survey Fee:

Transportation: _____ S + RS. SI

), Fuel

), Others

TOTAL

Add Fee: : Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Report Format: DAR

Lump Sum / I.B.I: (\$

Part 5143P

Hyundai Elantra

Rec	Bumper	Pr	\$ 481.40	—
↳	↳ reinforcement	Pr	\$ 294.80	—
↳	↳ clips	Pr	\$ 50.00	—
↳	↳ lower garnish	Pr	\$ 340.60	—
↳	↳ reverse sensor	Short	\$ 200.00	—
↳	↳ end panel	R	\$ 525.00	X

20%

Labor to paint heat the above	\$ 400
↳ " Spray paint affected parts	\$ 400
Check wiring	\$ 150
Remove & rebit reverse sensor	\$ 50