

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
	HSBC LIFE (SINGA	APORE) PTE LTD	Ref:	CS3/HSB23005475/Kqp3e2
	10 MARINA BOULE #48-01 MARINA BA 2SINGAPORE 0189	AY FINANCIAL CENTRE TOWER	Date:	21/06/2023
	ATTN: OH VALE		Code:	HSB
1.	Policy Particulars :- (THIRD PARTY CLAIM)			
	Insured Veh.	SHC 3040D	Veh. Inspected	SME 2945E
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S3M04MV8	Excess (\$)	0.00
	Assign From	OH VALE	Assign Date	30/05/2023
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI ELANTRA (A)	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	KMHD841CMJU754204	Colour	METALLIC SILVER
	Odometer	222666 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	VIKING	8 mm
	L/H Front Tyre	195/65 R15	VIKING	8 mm
	R/H Rear Tyre	195/65 R15	VIKING	8 mm
	L/H Rear Tyre	195/65 R15	VIKING	8 mm
4. Description of Damages				
	THE VEHICLE SUS	CLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.		
5.	General Information			
	Accident Date	25/05/2023	Inspect Date / Time	16/06/2023 (01:23 PM)
	Survey held at	YAP MOTOR REPAIR SERVICE		
	BLK 7 SIN MING IND EST SEC C #01-80 & 82 SINGAPORE 575642			
5a.	Remarks			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days			

Report Ref No. CS3/HSB23005475/Kqp3e2

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser