

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/AIS23005489/UNP3Q2**Date:** 14/06/2023**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SKF4095M**Insured Vehicle No :** SLR854R

Date of Loss: 01/05/2023

Nature of Claim: TP Claim No: N/A

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SKF4095M**

Make &amp; Model: HONDA STREAM, 1.7 (A)

Engine No: R18A1800780

Reg. Date: 25/11/2010 (Man. Year: 2008)

Chassis No: RN61090841

Colour: Black

Odometer: 127381 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/65 R15

Rear Tyre Size: 205/65 R15

Front Left Side: Firenza 6 mm

Rear Left Side: Firenza 6 mm

Front Right Side: Firenza 6 mm

Rear Right Side: Firenza 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	562.32	562.32	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	600.00	700.00	53.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>1,862.32</b>	<b>1,162.32</b>	<b>700.00</b>	<b>37.59</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>900.00</b>		
<b>Nett Amount (S\$)</b>	<b>1,862.32</b>	<b>900.00</b>	<b>962.32</b>	<b>51.67</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

**INSPECTION**

Date of Assignment: 30/05/2023

Date Inspected: 31/05/2023 Inspected At:

EEVolveauto Workshop LLP (HQ)  
1 Kaki Bukit Avenue 6, #02-25 Autobay @ Kakit  
Bukit  
Singapore 417883

Estimated Period of Repair: 2.0 days

**Adjuster:** MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jun 2023)
Parts:	M1-MPV	HONDA STREAM 1.7 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKF4095M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT (NPA)	Not Necessary	0.00 FL	*- FL
2	1		*BOOT WEATHERSTRIP (NPA)	Not Necessary	0.00 FL	*- FL
3	1		*REAR BUMPER	Deformed / Torn	665.40 FL	*665.40 FL
4	1		*REAR BUMPER LHS RETAINER (NPA)	Not Necessary	0.00 FL	*- FL
5	1		*REAR LEFT TAIL LAMP (NPA)	Not Necessary	0.00 FL	*- FL
6	1		*SET BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
					Sub Total (\$\$)	695.40 695.40
					- List Item Discount on L Items 20.00/20.00% (\$\$)	133.08 133.08
					Total Parts (\$\$)	562.32 562.32

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE ,REPAIR & REPLACE	New	650.00	200.00
2	SPRAY PAINTING	New	650.00	400.00
<b>Gross Labour Cost (S\$)</b>			<b>1,300.00</b>	<b>600.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >