

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	INCOME INSURAN	ICE LTD		Ref:	CS3/INC23005495/Tvy3e2
	75 BRAS BASAH R	ROAD SINGAPORE 189557		Date:	12/06/2023
	ATTN: MARCUS X	IAO		Code:	INC
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SKB 9652T	Veh. Inspected		SKR 3529Y
	Policy No.		Coverage (\$)		0.00
	Claim No.	MT/1224419-002	Excess (\$)		0.00
	Assign From	HAZALYSA	Assign Date		30/05/2023
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ C180	c.c		1595
	Engine No.	HIDDEN	Year of Reg.		2015
	Chassis No.	WDD2050402R042685	Colour		SILVER
	Odometer	133881 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	225/50 R17	PIRELLI		6 mm
	L/H Front Tyre	225/50 R17	PIRELLI		6 mm
	R/H Rear Tyre	225/50 R17	PIRELLI		6 mm
	L/H Rear Tyre	225/50 R17	PIRELLI		6 mm
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR PORTION.			
5.	General Information				
	Accident Date	20/05/2023	Inspect Date / 1	Гіте	06/06/2023 (12:00 PM)
	Survey held at	TRIDENT AUTO SERVICE CENTRE PTE LTD			
		8 KAKI BUKIT AVENUE 4, #02-42, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/INC23005495/Tvy3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser