

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123005496/UQY3Q2**Date:** 14/07/2023REFERENCE

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMCG22014700
Claimant Vehicle No :	GZ2227E	Insured Vehicle No :	GBK7752K
Date of Loss:	26/05/2023	Nature of Claim:	TP
		Claim No:	CDMCG23001314

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GZ2227E	Engine No:	K9KE628D660164
Make & Model:	NISSAN NV200, 1.5 MT (M)	Chassis No:	VSKYBAM20Z0176732
Reg. Date:	11/04/2019 (Man. Year: 2018)	Odometer:	63447 km
Colour:	Blue		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,493.16	842.22	650.94	43.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,690.00	790.00	900.00	53.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,183.16	1,632.22	1,550.94	48.72
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	3,183.16	1,300.00	1,883.16	59.16
+ GST 8.00/8.00% (S\$)	254.65	104.00	150.65	59.16
Nett Amount (S\$)	3,437.81	1,404.00	2,033.81	59.16

INSPECTION

Date of Assignment:	30/05/2023	Hock Wah Motor Workshop Pte Ltd (Bedok)
Date Inspected:	12/06/2023 Inspected At:	Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012
Estimated Period of Repair:	3.0 days	Singapore 489977

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 13 Jul 2023)	
Parts:	N/A	NISSAN NV200 1.5 MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GZ2227E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Badly Dented	617.80 FN	*617.80 FN
2	1		*FRONT FENDER SIGNAL LAMP RH	Broken	60.80 FN	*60.80 FN
3	1		*FRONT FENDER INNER SHIELD RH	Twisted	114.20 FN	*114.20 FN
4	1		*FRONT QUARTER GLASS GARNISH	Grazed	267.20 FN	*118.00 FN
5	5		*FRONT FENDER INNER SHIELD CLIP RH	Necessary	25.00 FN	*25.00 FN
6	1		*FRONT WHEEL RIM COVER RH	Repair	162.70 FN	*- FN
7	1		*FRONT WHEEL HUB BEARING RH	Not Necessary	384.70 FN	*- FN
8	1		*FRONT DOOR RH (NPA)	Repair	0.00 FS	*- FS
9	1		*QUARTER GLASS SEALANT	Not Necessary	24.00 FS	*- FS
						F=Franchise part. S=SpcNett. N=NettItemDisc.
Sub Total (S\$)					1,656.40	935.80
- Nett Item Discount on N Items 10.00/10.00% (S\$)					163.24	93.58
Total Parts (S\$)					1,493.16	842.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	600.00	300.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	600.00	400.00
3	ANTI -RUST COATING	New	80.00	30.00
4	TO REMOVE & REFIT UNDERCARRIAGE	New	250.00	0.00
5	TWO WHEEL ALIGNMENT	New	80.00	60.00
6	TO REMOVE & REFIT QUARTER GLASS	New	80.00	0.00
Gross Labour Cost (S\$)			1,690.00	790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >