

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS23005506/KYA3Q2**Date:** 07/07/2023REFERENCE

| | | | |
|------------------------------|---------------------------------------|-----------------------------|--------------|
| Handling Insurer: | Allianz Insurance Singapore Pte. Ltd. | Policy No: | SP2003573972 |
| Claimant Vehicle No : | SLF4564P | Insured Vehicle No : | SMT9614K |
| Date of Loss: | 22/05/2023 | Nature of Claim: | TP |
| | | Claim No: | 202332008668 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|--------------------------------------|-------------|--------------|
| Reg No: | SLF4564P | Engine No: | 3ZRB804297 |
| Make & Model: | TOYOTA HARRIER, 2.0 ELEGANCE CVT (A) | Chassis No: | ZSU600081025 |
| Reg. Date: | 26/08/2016 (Man. Year: 2016) | Odometer: | 109456 km |
| Colour: | Metallic Black | | |
| Engine Capacity: | 1986 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size: | 225/55 R18 | Rear Tyre Size: | 225/55 R18 |
| Front Left Side: | Bridgestone 8 mm | Rear Left Side: | Bridgestone 9 mm |
| Front Right Side: | Bridgestone 8 mm | Rear Right Side: | Bridgestone 9 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 7,469.56 | 3,338.54 | 4,131.02 | 55.30 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,610.00 | 1,070.00 | 1,540.00 | 59.00 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 10,079.56 | 4,408.54 | 5,671.02 | 56.26 |
| Approved Total (Overridden) (S\$) | | 3,500.00 | | |
| Nett Amount (S\$) | 10,079.56 | 3,500.00 | 6,579.56 | 65.28 |
| Global Sum Settlement (S\$) | | 0.00 | | |

INSPECTION

| | | |
|-----------------------------|--------------------------|---|
| Date of Assignment: | 30/05/2023 | Sin Ming Autocare BFG Pte Ltd (HQ) |
| Date Inspected: | 06/06/2023 Inspected At: | 176, Sin Ming Drive #02-05, Sin Ming Autocare Complex |
| Estimated Period of Repair: | 4.0 days | Singapore 575721 |

Adjuster: KENNETH KONG**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 07 Jul 2023) |
| Parts: | M1-SUV | TOYOTA HARRIER 2.0 ELEGANCE CVT (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SLF4564P) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|---------------|-------------|--------------|
| 1 | 1 | | *TAIL GATE | Bent | 2,126.40 FL | *2,126.40 FL |
| 2 | 1 | | *TAIL GATE WEATHERSTRIP | Serviceable | 446.90 FL | *- FL |
| 3 | 1 | | *TAIL GATE LOCK | Repair | 320.15 FL | *- FL |
| 4 | 1 | | *TAIL GATE EMBLEM LOGO | Not Necessary | 85.60 FL | *- FL |
| 5 | 1 | | *TAIL GATE EMBLEM HARRIER | Necessary | 123.15 FL | *123.15 FL |
| 6 | 1 | | *TAIL GATE GARNISH OUTER | Serviceable | 1,055.20 FL | *- FL |
| 7 | 1 | | *REAR BODY PANEL | *Check | 1,006.40 FL | *- FL |
| 8 | 1 | | *REAR BODY PANEL TOP GARNISH | Serviceable | 438.30 FL | *- FL |
| 9 | 1 | | *REAR BUMPER | Buckled | 1,744.70 FL | *1,744.70 FL |
| 10 | 1 | | *REAR BUMPER SIDE RETAINER LH | Serviceable | 85.60 FL | *- FL |
| 11 | 8 | | *REAR BUMPER LOWER COVER CLIPS | Necessary | 44.00 FL | *44.00 FL |
| 12 | 1 | | *REAR BUMPER REFLECTOR LH | Serviceable | 96.80 FL | *- FL |
| 13 | 1 | | *REAR WINDSCREEN MOULDING LOWER | Necessary | 101.50 FL | *101.50 FL |
| 14 | 1 | | *REAR WINDSCREEN MOULDING RH | Necessary | 60.50 FL | *60.50 FL |
| 15 | 1 | | *REAR WINDSCREEN MOULDING LH | Necessary | 60.50 FL | *60.50 FL |
| 16 | 1 | | *REAR BEZA SENSOR | Serviceable | 285.15 FL | *- FL |
| 17 | 1 | | *REAR BUMPER LOWER GARNISH | Serviceable | 566.66 FL | *- FL |
| 18 | 1 | | *REAR TAIL GATE REFLECTOR LH | Serviceable | 608.60 FL | *- FL |
| 19 | 1 | | *REAR BUMPER REVERSE SENSOR COVER LH CENTRE | Serviceable | 44.50 FS | *- FS |
| 20 | 1 | | *REAR GLASS SEALANT | Necessary | 50.00 FS | *40.00 FS |
| 21 | 1 | | *REAR REVERSE SENSOR SIDE LH | *Check | 280.00 FS | *- FS |
| 22 | 1 | | *REAR BUMPER SPONGE | Cracked | 137.30 FL | *137.30 FL |
| 23 | 1 | | *REAR GLASS SEALANT | Repeated | 50.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$) | 9,817.91 | 4,438.05 |
| - List Item Discount on L Items 25.00/25.00% (\$) | 2,348.35 | 1,099.51 |
| Total Parts (\$) | 7,469.56 | 3,338.54 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO DISMANTLE & REPLACE DAMAGE PARTS ,PANEL BEAT WHERE NECESSARY | New | 1,200.00 | 400.00 |
| 2 | TO PUTTY ,APPLY PRIMER & SPRAY PAINT ON AFFECTED PORTION | New | 1,000.00 | 440.00 |
| 3 | TO APPLY RUST PROOFING ON REPAIR | New | 80.00 | 30.00 |
| 4 | TO REMOVE/REFIT REAR GLASS TO FACILITATE REPAIRS | New | 150.00 | 120.00 |
| 5 | TO REMOVE /TRANSFER REAR TAILGATE MECHANISMS | New | 120.00 | 60.00 |
| 6 | TO CHECK WIRING FUNCTIONS | New | 60.00 | 20.00 |
| Gross Labour Cost (\$\$) | | | 2,610.00 | 1,070.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >