



KTO Automobile Assessors

Reg. No : 52941122M

470 Segar Road #09-232 Singapore 670470 Email: ktoa@singnet.com.sg HP: 98505311

INVOICE

M/S: Koh Tiong Wee (Guo ZhongWei)
C/O JL Auto Services Pte Ltd
Blk 3006 Ubi Road 1 #01-346
Singapore 408700

Invoice No : 21-08489

Invoice Ref : TP/JLA/SKV5713Y/8489

Date : 05 February 2021

DESCRIPTION	AMOUNT
For Services Rendered Inspection report fees inclusive of : Re-Inspection, Transportation & Photographs Twenty (20) copies. Vehicle No : SKV 5713 Y Make/Model : Mazda Mazda5 5-Door Wagon 2.0L SP.6EAT Sunroof	\$ 420.00
Singapore Dollars: Four Hundred And Twenty Only	\$ 420.00

Cheques should be made payable to KTO AUTOMOBILE ASSESSORS. Please indicate our Invoice No. on the reverse of your cheque.

KTO AUTOMOBILE ASSESSORS

Ong Ah Keng (CAE, AMIMI, MSAAA)
Automotive Appraiser

**ACCIDENT DAMAGED VEHICLE INSPECTION REPORT**

M/S : Koh Tiong Wee (Guo ZhongWei)
C/O JL Auto Services Pte Ltd
Blk 3006 Ubi Road 1 #01-346
Singapore 408700

Date : 05 February 2021
Our Ref : TP/JLA/SKV5713Y/8489

REFERENCE PARTICULARS

Date of Accident : 27 December 2020
Date of Inspection : 11 January 2021

Type of Inspection : Third Party Claim
Date of Re-Inspn : 15 January 2021

VEHICLE PARTICULARS

Registration No : SKV 5713 Y
Make : Mazda
Model : Mazda5 5-Door Wagon 2.0L SP.6EAT Sunroof
Year : 2015

Engine No : PE10246872
Chassis No : JM6CW1071G0122280
Odometer : 76584 km
Colour : Blue

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Foot Brake : Serviceable
Hand Brake : Serviceable

General Body Work : Good
Steering : Serviceable
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front Near side	: Yokohama	195/60R16	6 mm
Front Off Side	: Yokohama	195/60R16	6 mm
Rear Near Side	: Yokohama	195/60R16	6 mm
Rear off Side	: Yokohama	195/60R16	6 mm

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the rear near side portion
For details, refer to assessment for repairs and photographs
attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **\$4,500.00 nett** at lump sum basis.(Subject to GST if applicable)

Under normal circumstances, estimated period required for repairs : Five (5) working days.

Enclosed Twenty (20) photographs depicting damage to the vehicle and after repair.

Inspection conducted at : JL Auto Services Pte Ltd
Blk 3006 Ubi Road 1 #01-346 Singapore 408700

In accordance to your instruction, we have **not authorise** repairs and inspection
was conducted strictly on a "**WITHOUT PREJUDICE BASIS**".

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

Automobile Consultants, Insurance Loss Assessors/Adjusters, Inspection and Evaluation

POINT OF IMPACT

The impact was confined to the rear near side portion of the vehicle.

The damages appeared to be consistent as per the accident report statement.

Please refer the attached schedule and photographs for details.

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **\$4,500.00 nett** corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully

KTO Automobile Assessors



Ong Ah Keng (CAE, AMIMI, MSAAA)
Automotive Appraiser

JL Auto Services Pte Ltd

Blk 3006 Ubi Road 1 #01-346 Singapore 408700 HP : 91885495

M/S : Koh Tiong Wee (Guo ZhongWei)
Blk 670 #12-45 Jalan Damai
Eunos Damai Ville
Singapore 410670

Date : 05 February 2021

Tax Invoice : JLA/SKV5713Y/TP218489

Vehicle No : SKV 5713 Y

Make/Model : Mazda Mazda5 5-Door Wagon 2.0L

Date of accident : 27.12.2020

PARTICULAR	Amount
Rear Right Side Portion Damaged Parts replacement, remove & reinstall, repair, Panel beating, labour and spray-painting, etc.	
Lump-sum repair cost as per surveyor report recommendation -----	\$ 4,500.00

Singapore Dollars : Four Thousand Five Hundred Only

Total \$ 4,500.00 Nett



JL Auto Service Pte Ltd