

**ACCIDENT DAMAGED VEHICLE INSPECTION REPORT**

M/S : Koh Tiong Wee (Guo ZhongWei)  
C/O JL Auto Services Pte Ltd  
Blk 3006 Ubi Road 1 #01-346  
Singapore 408700

Date : 05 February 2021  
Our Ref : TP/JLA/SKV5713Y/8489

**REFERENCE PARTICULARS**

Date of Accident : 27 December 2020  
Date of Inspection : 11 January 2021

Type of Inspection : Third Party Claim  
Date of Re-Inspn : 15 January 2021

**VEHICLE PARTICULARS**

Registration No : SKV 5713 Y  
Make : Mazda  
Model : Mazda5 5-Door Wagon 2.0L SP.6EAT Sunroof  
Year : 2015

Engine No : PE10246872  
Chassis No : JM6CW1071G0122280  
Odometer : 76584 km  
Colour : Blue

**CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)**

Engine condition : Good  
Foot Brake : Serviceable  
Hand Brake : Serviceable

General Body Work : Good  
Steering : Serviceable  
Lightings : Serviceable

**TYRE CONDITION (Remaining estimated life of tyre in mm)**

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front Near side	: Yokohama	195/60R16	6 mm
Front Off Side	: Yokohama	195/60R16	6 mm
Rear Near Side	: Yokohama	195/60R16	6 mm
Rear off Side	: Yokohama	195/60R16	6 mm

**GENERAL DESCRIPTION OF DAMAGES**

The vehicle sustained damage at the rear near side portion  
For details, refer to assessment for repairs and photographs  
attached.

**ASSESSMENT SUMMARY**

Our assessment of the repair costs to pre-accident condition was **\$4,500.00 nett** at lump sum basis.(Subject to GST if applicable)

Under normal circumstances, estimated period required for repairs : Five (5) working days.

Enclosed Twenty (20) photographs depicting damage to the vehicle and after repair.

Inspection conducted at : JL Auto Services Pte Ltd  
Blk 3006 Ubi Road 1 #01-346 Singapore 408700

In accordance to your instruction, we have **not authorise** repairs and inspection  
was conducted strictly on a "**WITHOUT PREJUDICE BASIS**".

### DESCRIPTION OF PARTS AND NATURE OF REPAIRS

Automobile Consultants, Insurance Loss Assessors/Adjusters, Inspection and Evaluation

**POINT OF IMPACT**

The impact was confined to the rear near side portion of the vehicle.

The damages appeared to be consistent as per the accident report statement.

Please refer the attached schedule and photographs for details.

**ADJUSTMENT/RECOMMENDATIONS**

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

**CONCLUSION**

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **\$4,500.00 nett** corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully

KTO Automobile Assessors



---

Ong Ah Keng (CAE, AMIMI, MSAAA)  
Automotive Appraiser