

Acc. Pkg. By:

REF:

CS/LAW 23005511/Day 3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Velt: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bel. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 7/P % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SNK 8080S Yr Regn: Sept, 2015

Type: MC / MCycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: MCZ 5 CC: 1998

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 101288 T/Radio: Insured / Std / NI / NA

Eng No: PE 10246872

C/Nr: JM6CW1071G0122280

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 216

R: 11

BS / DUN / EXNOVA / GY / FS / LZA / MEC / OHTSU / PIR / SUMI /

TOYO / YOKO or Yokohama

Front _____ Rear _____

R/Bal: 5 mm R/Bal: 5 mm

L/Bal: 5 mm L/Bal: 5 mm

D.O.A: 27/12/2020 D.O.I: 31/07/2023

Survey held at BLK 670 Jalan Demai

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>SOB Physical Re-inspection</u>
<u>01/08/23</u>	<u>To submit 7/P 1766-16 with 3 days of rep: (Red \$233.84, 60%)</u>

Date/Time, File Pass to?

☐ : Prel. Report
☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

Report Formes:

TR

1) prior 9 am 11 P to 12

\$1766.16

Bryan Ang (LKKAUTO)

SJB

From: Muhammad Hazdi Bin Hasni <hazdi.hasni@kcpartnership.com>
Sent: Monday, 29 May 2023 5:53 pm
To: Bryan Ang (LKKAUTO); rajes@yoga-legal.com; Sheikh Eusoff; admin-d
Cc: Insurance Admin; Sarjeet Singh; hazdi.hasni@kcpartnership.com; Vithyanagan Pandian
Subject: Appointment of SJE // MC/MC 3918/2021 // C Yogarajah Ref : CY.11330.21.JLA.(PD-HW).wp.rj// KCP Ref: SS/sm/2021000709 Sompo(mpd)
Attachments: Order of Court (03.04.23).pdf
Importance: High

Email sent for and on behalf of Mr Sarjeet Singh, Kelvin Chia Partnership

Attention Mr Bryan Ang

MC/MC 3918/2021

Dear Sirs,

We refer to the above matter.

M/s C Yogarajah LLC (copied herein) act for the Plaintiff (Owner of SKV 5713Y) and we act for the 1st and 2nd Defendant (Owner and Driver of GBC 3401S).

Please be informed that the Court has appointed you, Mr Bryan Ang, as the Single Joint Expert ("SJE") for this matter.

We enclose herewith copies of the following documents for your attention, kindly access the documents via dropbox link:

<https://www.dropbox.com/scl/fo/gj17pke1pxtgk4q50lpbz/h?dl=0&rlkey=lejsxvi29pspyvzdjw6yolzx0>

Singapore Accident Statement of SKV 5713Y dated 28 December 2020 (with coloured photographs);

Singapore Accident Statement of GBC 3401S dated 13 January 2021 (with coloured photographs);

Priority Services Paper survey report dated 22nd April 2021

Priority Services Pre repair survey dated 16th January 2021 (with coloured Photographs)

KTO Automobile Assessors Vehicle Inspection Report dated 5th February 2021

Please liaise with M/s C Yogarajah LLC (copied herein) for any other documents and arrange for a physical re-inspection (if required) of SKV 5713Y and thereafter prepare an SJE report to record your findings.

Note that we have inadvertently omitted to write to you with regards to the appointment. For your reference, we attached herein the Order of Court dated 3 April 2022.

In lieu of your appointment, kindly let us have the SJE Report of Motor vehicle no. SKV 5713Y **urgently**.

10 Sin Ming Drive Singapore 575701
www.lta.gov.sg

04 Jan 2023

Our ref 0401230203N061123249

KOH TIONG WEE (GUO ZHONGWEI)
APT BLK 670 JALAN DAMAI
#12-45
SINGAPORE 410670

Dear Sir/Madam

**You Have Successfully Replaced Vehicle Registration No. SKV5713Y
With SNK8080S**

You have successfully replaced your vehicle registration number. The vehicle, whose previous number was SKV5713Y, now has the number SNK8080S.

What You Need To Do:

- You must show the new number SNK8080S on your vehicle by 07 Jan 2023.

The vehicle details after the transaction are:

Transaction No. : 20230104123042732573
Vehicle Registration No. : SNK8080S (Previously SKV5713Y)
Vehicle Make : MAZDA
Vehicle Model : MAZDA5 5-DOOR WAGON 2.0L
SP.6EAT SUNROOF
Chassis No. : JM6CW1071G0122280
Engine No./ Motor No. : PE10246872 / -

Please change the number plates on this vehicle to show SNK8080S by 07 Jan 2023. Otherwise, it is an offence and the penalty is a fine of up to \$2,000 or imprisonment of up to 6 months, or both.

**ACCIDENT DAMAGED VEHICLE INSPECTION REPORT**

M/S : Koh Tiong Wee (Guo ZhongWei)
C/O JL Auto Services Pte Ltd
Blk 3006 Ubi Road 1 #01-346
Singapore 408700

Date : 05 February 2021
Our Ref : TP/JLA/SKV5713Y/8489

REFERENCE PARTICULARS

Date of Accident : 27 December 2020
Date of Inspection : 11 January 2021

Type of Inspection : Third Party Claim
Date of Re-Inspn : 15 January 2021

VEHICLE PARTICULARS

Registration No : SKV 5713 Y
Make : Mazda
Model : Mazda5 5-Door Wagon 2.0L SP.6EAT Sunroof
Year : 2015

Engine No : PE10246872
Chassis No : JM6CW1071G0122280
Odometer : 76584 km
Colour : Blue


CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Foot Brake : Serviceable
Hand Brake : Serviceable

General Body Work : Good
Steering : Serviceable
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front Near side	: Yokohama	195/60R16	6 mm
Front Off Side	: Yokohama	195/60R16	6 mm
Rear Near Side	: Yokohama	195/60R16	6 mm
Rear off Side	: Yokohama	195/60R16	6 mm

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the rear near side portion
For details, refer to assessment for repairs and photographs
attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **\$4,500.00 nett** at lump sum basis. (Subject to GST if applicable)

Under normal circumstances, estimated period required for repairs : Five (5) working days.

Enclosed Twenty (20) photographs depicting damage to the vehicle and after repair.

Inspection conducted at : JL Auto Services Pte Ltd
Blk 3006 Ubi Road 1 #01-346 Singapore 408700

In accordance to your instruction, we have **not authorise** repairs and inspection
was conducted strictly on a "**WITHOUT PREJUDICE BASIS**".

MAKE/MODEL : MAZDA MAZDA5 5-DOOR WAGON 2.0L SP.6EAT SUNROOF

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS**DESCRIPTION OF PARTS AND NATURE OF REPAIRS**

A)	SPARE PARTS	QTY PC/SET	ASSESSED CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
1	Rear bumper	1	Deformed	\$ 961.00	\$ 961.00 <i>HN</i>
2	Rear bumper reinforcement	1	Serviceable	\$ 275.30	~ <i>HN</i>
3	Rear bumper side retainer L/R @ \$62.50	2	LH only (Cracked)	\$ 125.00	\$ 62.50 <i>HN</i>
4	Rear bumper bracket L/R @ \$22.50	2	LH only (Bent)	\$ 45.00	\$ 22.50 <i>HN</i>
5	Rear tail gate	1	Dented	\$ 1,637.00	\$ 1,637.00 <i>R</i>
6	Rear tail gate weather-strip	1	Serviceable	\$ 197.90	~
7	Rear tail gate lock	1	Serviceable	\$ 292.70	~
				\$ 3,533.90	\$ 2,683.00
			Less 20%	\$ 706.78	\$ 536.60
				\$ 2,827.12	\$ 2,146.40
B)	<u>S/NETT ITEM</u>				
8	Rear bumper clips	1 set	Necessary	\$ 34.00	\$ 34.00 <i>HN</i>
9	Rear tail gate lamp LH	1	Cracked	\$ 419.00	\$ 419.00 <i>✓</i>
10	Rear tail lamp LH	1	Cracked	\$ 690.60	\$ 690.60 <i>✓</i>
11	Rear windscreen glass moulding	1	Necessary	\$ 130.60	\$ 130.60 <i>HN</i>
12	Rear windscreen glass spacer	1	Necessary	\$ 29.00	\$ 29.00 <i>HN</i>
13	Rear tail gate 'Mazda' logo	1	Necessary	\$ 53.70	\$ 53.70 <i>✓</i>
14	Rear tail gate 'Mazda5' emblem	1	Necessary	\$ 53.00	\$ 53.00 <i>✓</i>
15	Rear tail gate 'SKYACTIV' emblem	1	Necessary	\$ 53.90	\$ 53.90 <i>✓</i>
16	Rear bumper reverse sensor L/R @ \$193.90	2	1 pc only (Malfunction)	\$ 387.80	\$ 193.90 <i>HN</i>
	Parts Total :			\$ 4,678.72	\$ 3,804.10
C)	<u>LABOUR CHARGES & MISC</u>				
17	Spray painting on above new & repaired parts including supply of paint materials.			\$ 800.00	\$ 700.00 <i>200/-</i>
18	Remove damaged parts, straighten, knock out dents, panel beating, remove, reinstall necessary fittings to facilitate repairs, adjust, replace and realign all relevant parts.			\$ 850.00	\$ 750.00 <i>400/-</i>
19	To cavity preservation on all affected areas.			\$ 100.00	\$ 60.00 <i>20/-</i>
20	To transfer rear tail gate mechanism & component.			\$ 80.00	\$ 50.00 <i>HN</i>
21	To remove & reinstall rear windscreen glass to assist repair.			\$ 120.00	\$ 120.00 <i>HN</i>
22	Check wiring, lighting, reconnection socket, wiper motor & central locking system for proper function.			\$ 50.00	\$ 30.00 <i>✓</i>
23	To reinstall rear bumper sensor and check for proper function.			\$ 120.00	\$ 80.00 <i>HN</i>
24	To supply rear windscreen glass sealant.			\$ 50.00	\$ 40.00 <i>HN</i>
	Labour Total :			\$ 2,170.00	\$ 1,830.00
	Total Parts and Labour			\$ 6,848.72	\$ 5,634.10

FINAL LUMP SUM ADJUSTMENT**\$ 4,500.00**

* Rear Bumper photo shows no damage. Pns
herent y lorry not do not suggest can
touch for bump

3/P 1766.16
3 dep.

* Tailgate paint coat show not changed.

Automobile Consultants, Insurance Loss Assessors/Adjusters, Inspection and Evaluation

* No used parts and all part repairs need to change, so 3/P.

MAKE/MODEL : MAZDA MAZDA5 5-DOOR WAGON 2.0L SP.6EAT SUNROOF

POINT OF IMPACT

The impact was confined to the rear near side portion of the vehicle.

The damages appeared to be consistent as per the accident report statement.

Please refer the attached schedule and photographs for details.

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **\$4,500.00 nett** corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully

KTO Automobile Assessors



Ong Ah Keng (CAE, AMIMI, MSAAA)
Automotive Appraiser