



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SBZ 1188A

Qty	Description of Parts	Condition	Recommended (\$)
	<u>REPLACEMENT OF PARTS</u>		
1	REAR MUDFLAP (WCP)	NOT NECESSARY	-
1	REAR RH FENDER (WCP)	DENTED	680.00
1	REAR WINDSCREEN MOULDING (WCP)	NECESSARY	45.00
1	REAR RH SHOCK ABSORBER (WCP)	BENT	175.00
1	REAR RH WHEEL HUB (WCP)	BENT	150.00
1	REAR AXLE (WCP)	BENT	780.00
	COST PLUS 10%		183.00
			2,013.00
	<u>SPECIAL NETT ITEMS</u>		
1	REAR RH SPORTS RIM (LOCAL REPAIR) (SN)	CUT	100.00
1	REAR RH TYRE (SN)	SERVICEABLE	-
1	REAR WINDSCREEN GUM (SN)	NECESSARY	40.00
			140.00
	<u>LABOUR</u>		
	WIRE CHECKING.		20.00
	REMOVE & REFIX REAR WINDSCREEN.		100.00
	REMOVE & REFIX CUSHION AND SEATS.		150.00
	REMOVE & REFIX REAR UNDERCARRIAGE (WITH AXLE).		300.00
	4 WHEEL ALIGNMENTS.		140.00
	LABOUR CHARGE.		600.00
	SPRAY PAINTING.		450.00
			1,760.00
GRAND TOTAL			3,913.00
RECOMMENDED COST OF REPAIRS			3,913.00

Report Ref No. CS1/SCD23005523/Uqy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.