

ESTIMATE OF REPAIR

Veh# : GBE6527H

Accident Date : 21/5/2023

Location : LORONG AH SOO BLK 105 MULTI-STOREY CARPARK

Model: TOYOTA HILUX D CAB

(24/10/2012 - 31/8/2027)

3P: SLK4744K (AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear door RH <i>Dented</i>	1859.70	<i>1280</i>	
2	1 pc	Rear door inner trim board RH <i>crushed</i>	893.90	<i>550</i>	
3	1 set	Rear door inner trim board clip RH <i>new</i>		50.00	<i>30</i>
4	1 pc	Rear door weatherstrip RH <i>new</i>	165.30	X	
5	1 pc	Rear door plastic seal cover RH <i>new</i>	38.60	X	
6	1 pc	Rear door end panel RH <i>Dented</i>	1331.00	<i>745</i>	
7	1 pc	Rear side panel RH <i>Repair</i>	1466.00	X	
8	1 pc	Rear side panel inner shield RH <i>new</i>	151.10	X	
9	1 set	Rear side panel inner shield clip RH <i>new</i>		50.00	X
10	1 pc	Rear side panel mudflap RH <i>new</i>	111.20	X	
11	1 pc	Rear tyre RH <i>new</i>		250.00	X
12	1 pc	Rear wheel rim RH <i>at</i>	2686.20	<i>700 (SN)</i>	
13	1 pc	Rear wheel bearing RH <i>new</i>	52.20	X	
		<i>2615 SN: 700</i> Sub-Total:	8,755.20	350.00	0.00
		<i>1961.25</i>	25%	0%	0%
		After Less %:	6,566.40	350.00	0.00
		Labour			
1		To remove & refix accident damaged parts & realign affected area.	1,400.00	<i>800</i>	
2		To spray paint on accident affected area.	1,000.00	<i>700</i>	
3		To rust proof affected area.	120.00	<i>50</i>	
4		To computerise wheel alignment	120.00	<i>80</i>	
5		To remove & refix door mechanism & check for function.	60.00	✓	
		Sub-Total:		2,700.00	
		Total:		9,616.40	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No financial claim/claim allowed
- Supplemental(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer



total: 4351.25 Admin Lin
4/s: 3.41k. 1/s 05/06/23.05
days.