

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 8722R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	1,974.00	1,410.00
1	FRONT BUMPER RETAINER LH	DETACHED	213.00	164.00
1	FRONT BUMPER RETAINER RH	DETACHED	213.00	164.00
1	FRONT BUMPER GRILLE	GRAZED	957.50	766.00
1	FRONT BUMPER GRILLE LOGO	NECESSARY	259.00	185.00
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	364.00	-
1	FRONT BUMPER FOGLAMP LH	NOT NECESSARY	493.70	-
1	FRONT BUMPER FOGLAMP LOWER GRILLE LH	NOT NECESSARY	313.60	-
1	HEADLAMP LH	CRACKED	3,537.30	1,605.00
1	HEADLAMP NOZZLE LH	NOT NECESSARY	460.00	-
1	HEADLAMP NOZZLE COVER LH	DEFORMED	173.60	124.00
1	FRONT SUPPORT PANEL	NOT NECESSARY	590.20	-
	LESS 10% DISCOUNT		-954.89	-441.80
			8,594.01	3,976.20
	SPECIAL NETT ITEMS			
1	FRONT BUMPER CLIPS (SN)	NECESSARY	100.00	30.00
2	FRONT SENSOR (SN)	NOT NECESSARY	898.00	-
1	FRONT NUMBER PLATE (SN)	NECESSARY	80.00	40.00
1	FRONT GRILLE CLIPS (SN)	NECESSARY	100.00	20.00
			1,178.00	90.00
	<u>LABOUR</u>			
	PANEL BEATING.		1,400.00	300.00
	TO CHECK LIGHTING AND WIRING.		200.00	30.00
	TO DIAGNOSTIC CHECK.		350.00	100.00
	TOWING CHARGE.		200.00	80.00
	TO SPRAY PAINTING.		1,400.00	400.00
			3,550.00	910.00
	GRAND TOTAL		13,322.01	4,976.20

Report Ref No. CS3/SMR22007855/Dny3m4-1



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS3/SMR22007855/Dny3m4-1



Automotive Assessor / Investigator