

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23005530/TVP3Q2**Date:** 03/08/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00172502202

Claimant Vehicle No : YP7529R **Insured Vehicle No :** SDL10K

Date of Loss: 14/02/2023 Nature of Claim: TP Claim No: SNM23D201193/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YP7529R**

Make & Model: MITSUBISHI CANTER, 3.0 D FEB21ER4SDEB (CBU) (M) Engine No: 4P10C75328

Reg. Date: 26/10/2017 (Man. Year: 2017) Chassis No: FEB21EA21601

Colour: White Odometer: 287533 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/85 R15 Rear Tyre Size: 195/85 R15 (D)

Front Left Side: Falken 6 mm Rear Left Side: Falken 6/6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,856.50	3,729.00	22,127.50	85.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,230.00	2,130.00	5,100.00	70.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,086.50	5,859.00	27,227.50	82.29
Approved Total (Overridden) (S\$)		4,700.00		
(S\$)	33,086.50	4,700.00	28,386.50	85.79
+ GST 8.00/8.00% (S\$)	2,646.92	376.00	2,270.92	85.79
Nett Amount (S\$)	35,733.42	5,076.00	30,657.42	85.79

INSPECTION

Date of Assignment: 31/05/2023

Date Inspected: 31/05/2023 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 03 Aug 2023)	
Parts:	N/A	mitsubishi canter 3.0 d feb21er4sdeb (cbu) (m) (model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP7529R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*RH TAILLAMP ASSY	Cracked	360.00 FL	*260.00 FL
2	1	*LH TAILLAMP ASSY	Not Necessary	360.00 FL	*- FL
3	1	*REAR NUMBER PLATE LAMP	Not Necessary	93.00 FL	*- FL
4	1	*AIR CLEANER UPPER DUCT	Deformed	212.00 FL	*212.00 FL
5	1	*AIR CLEANER BOX	Not Necessary	854.00 FL	*- FL
6	1	*RADIATOR SPARE TANK	Not Necessary	163.00 FL	*- FL
7	1	*AIR CLEANER DUCT FLEX HOSE	Not Necessary	132.00 FL	*- FL
8	1	*WOODEN TAILGATE	Cracked	2,200.00 FS	*800.00 FS
9	1	*WOODEN TAILGATE FRAME	Bent	1,850.00 FS	*800.00 FS
10	1	*WOODEN TAILGATE LOWER MEMBER	Cracked	1,600.00 FS	*500.00 FS
11	1	*SET WOODEN TAILGATE LOWER MEMBER FASTENERS	Necessary	150.00 FS	*100.00 FS
12	1	*WOODEN TAILGATE 60KM/H STICKER	Necessary	28.00 FS	*25.00 FS
13	1	*WOODEN TAILGATE 23 PAX STICKER	Necessary	28.00 FS	*25.00 FS
14	1	*WOODEN TAILGATE RH SIDE HINGE	Bent	340.00 FS	*160.00 FS
15	1	*WOODEN TAILGATE RH CENTRE HINGE	Not Necessary	340.00 FS	*- FS
16	1	*WOODEN TAILGATE LH CENTRE HINGE	Not Necessary	340.00 FS	*- FS
17	1	*WOODEN TAILGATE LH SIDE HINGE	Not Necessary	340.00 FS	*- FS
18	1	*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
19	1	*WOODEN STEP	Not Necessary	580.00 FS	*- FS
20	1	*REAR RH CHASSIS WOODEN MEMBER	Not Necessary	1,600.00 FS	*- FS
21	1	*SET REAR RH CHASSIS WOODEN MEMBER FASTENERS	Not Necessary	220.00 FS	*- FS
22	1	*REAR LH CHASSIS WOODEN MEMBER	Not Necessary	1,600.00 FS	*- FS
23	1	*SET REAR LH CHASSIS WOODEN MEMBER FASTENER	Not Necessary	220.00 FS	*- FS
24	1	*REAR PLATFORM WOODEN MEMBERS (8 PCS)	Cracked (3 PCS ONLY)	440.00 FS	*165.00 FS
25	1	*REAR STEP BRACKET	Not Necessary	1,400.00 FS	*- FS
26	1	*WOODEN FRONT GATE	Not Necessary	2,200.00 FS	*- FS
27	1	*WOODEN FRONT GATE FRAME	Not Necessary	1,850.00 FS	*- FS
28	1	*WOODEN FRONT GATE GUARD	Not Necessary	1,850.00 FS	*- FS
29	1	*RH SIDE WOODEN GATE	Cracked	2,800.00 FS	*800.00 FS
30	1	*RH SIDE WOODEN GATE FRAME	Not Necessary	2,200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	26,400.00	3,847.00
- List Item Discount on L Items 25.00/25.00% (S\$)	543.50	118.00
Total Parts (S\$)	25,856.50	3,729.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS .TO PANEL BEATING ,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	3,200.00	900.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,800.00	700.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	100.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	180.00	0.00
5	LIFT UP WOODN PLATFORM TO ASSIST REPAIR AND REPLACE PARTS	New	1,200.00	300.00
6	LIFT UP REAR CANOPY ASSY TO ASSIST REPAIR	New	750.00	200.00
Gross Labour Cost (S\$)			7,230.00	2,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >