



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, Singapore 533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

INSURER: **ERGO Insurance Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCG23004473	Date of Loss:	27/05/2023
Vehicle Reg. No.:	GBJ4634T	Driveable?	
Driver Age/Info:	44 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	MKV ENGINEERING AND TRADING SERVICES PTE LTD	Contact No:	+6593362313
Driver:	SELVAMANI RANJITH		

Make/Model:	TOYOTA HIACE, 3.0 D DX TURBO MT 2WD 4DR (M)	Vehicle Reg. Date:	30/04/2019
Vehicle Colour:	WHITE	Chassis No:	JTFHT02P300248903
Engine No:	1KD2852059		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	21		
Description of Accident/Loss	REFER TO ATTACHE		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU) To check		

*Tanpin 97495749 / 62563561
Not Authorise Resurvey
Ex: \$500
14 days
Tanpin @ 1/14 auto work
Resurvey before/after paint*

COST OF CLAIMS

	Amount
Parts	17,537.30
Miscellaneous Items	120.00
Labour	3,010.00
Paintwork Labour	1,800.00
Towing	0.00
Calculated Gross Total (\$\$)	22,467.30
- Excess (\$\$)	500.00
(\$\$)	21,967.30
+ GST 8.00% (\$\$)	1,757.38
Nett Amount (\$\$)	23,724.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This claim is handled by: **MT TAN**

REPAIR DETAILS

Reference

(Last Synchronised: 31 May 2023)

Part Source: N/A TOYOTA HIACE 3.0 D DX TURBO MT 2WD 4DR (M) (Model not available in database)

Parts: N/A (Price-denominated Standard List)

Labour: Repairer's

Print Code: Kan Fook Sing Motor Workshop/GBJ4634T/31/05/2023 10:25

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WINDSCREEN GLASS	0.00	0.00	cur ✓ *480.00 F
2	1		*FRONT WINDSCREEN MOULDING	0.00	0.00	wh ✓ *40.00 F
3	1		*FRONT WIPER GARNISH	0.00	0.00	de ✓ *195.00 F
4	1		*FRONT WIPER CORNER GARNISH RH	0.00	0.00	de ✓ *15.00 F
5	1		*FRONT WIPER LINKAGE	0.00	0.00	? *150.00 F
6	1		*FRONT WIPER LINKAGE MOTOR	0.00	0.00	? *280.00 F
7	1		*FRONT WINDSCREEN PILLAR RH	0.00	0.00	? *225.00 F
8	1		*FRONT BONNET	0.00	0.00	bt ✓ *230.00 F
9	1		*FRONT BONNET LOCK	0.00	0.00	bt ✓ *45.00 F
10	1		*FRONT BONNET STOPPER RH	0.00	0.00	? *7.00 F
11	1		*FRONT BONNET STOPPER LH	0.00	0.00	? *7.00 F
12	1		*FRONT BONNET HINGE RH	0.00	0.00	bt ✓ *30.00 F
13	1		*FRONT BONNET HINGE LH	0.00	0.00	? *30.00 F
14	1		*FRONT BONNET CABLE	0.00	0.00	? *30.00 F
15	1		*FRONT CORNER PANEL RH	0.00	0.00	bt ✓ *65.00 F
16	1		*FRONT HEADLAMP RH	0.00	0.00	cur ✓ *245.00 F
17	1		*FRONT HEADLAMP LH	0.00	0.00	X *245.00 F
18	2		*FRONT HEADLAMP CLIP	0.00	0.00	wh ✓ *24.00 F
19	1		*FRONT GRILLE TOP	0.00	0.00	cur ✓ *95.00 F
20	1		*FRONT GRILLE LOWER	0.00	0.00	cur ✓ *145.00 F
21	1		*FRONT GRILLE BASE	0.00	0.00	cur ✓ *175.00 F
22	1		*FRONT SUPPORT PANEL	0.00	0.00	bt ✓ *155.00 F
23	1		*FRONT SUPPORT LOWER BRACKET RH	0.00	0.00	? *70.00 F
24	1		*FRONT SUPPORT LOWER BRACKET LH	0.00	0.00	X *70.00 F
25	1		*FRONT BRACE PANEL	0.00	0.00	? *30.00 F
26	1		*FRONT BUMPER	0.00	0.00	de ✓ *240.00 F
27	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	? *120.00 F
28	1		*FRONT BUMPER SIDE BRACKET RH	0.00	0.00	? *55.00 F
29	1		*FRONT BUMPER SIDE BRACKET LH	0.00	0.00	X *55.00 F
30	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	de ✓ *75.00 F
31	1		*FRONT BUMPER TOP BEAM	0.00	0.00	? *85.00 F
32	1		*FRONT BUMPER VERTICAL BRACKET RH	0.00	0.00	? *35.00 F
33	1		*FRONT BUMPER VERTICAL BRACKET LH	0.00	0.00	X *35.00 F
34	10		*FRONT BUMPER CLIP	0.00	0.00	wh ✓ *25.00 F
35	1		*INTERCOOLER	0.00	0.00	? *550.00 F
36	1		*INTERCOOLER GARNISH TOP	0.00	0.00	X *60.00 F
37	1		*INTERCOOLER GARNISH LOWER	0.00	0.00	? *55.00 F
38	1		*INTERCOOLER BRACKET	0.00	0.00	? *50.00 F
39	1		*WASHER TANK	0.00	0.00	X *65.00 F
40	1		*WASHER TANK MOTOR	0.00	0.00	X *75.00 F
41	1		*SPARE TANK	0.00	0.00	X *160.00 F
42	1		*BRAKE BOOSTER	0.00	0.00	? *520.00 F
43	1		*BRAKE BOOST BRAKE PIPE	0.00	0.00	? *80.00 F
44	1		*BRAKE MASTER PUMP	0.00	0.00	? *345.00 F
45	1		*BRAKE MASTER PUMP HOSE	0.00	0.00	? *120.00 F

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*CLUTCH PUMP	0.00	0.00	? *520.00 F
47	1		*DASHBOARD	0.00	0.00	? *520.00 F
48	1		*DASHBOARD REINFORCEMENT	0.00	0.00	? *350.00 F
49	1		*DASHBOARD LOWER COVER RH	0.00	0.00	de- *110.00 F
50	1		*STEERING COLUMN	0.00	0.00	? *550.00 F
51	1		*STEERING COUPLING	0.00	0.00	? *185.00 F
52	1		*STEERING BOX	0.00	0.00	? *480.00 F
53	1		*BRAKE PEDAL	0.00	0.00	? *300.00 F
54	1		*BRAKE SWITCH	0.00	0.00	? *65.00 F
55	1		*CLUTCH PEDAL	0.00	0.00	? *300.00 F
56	1		*AIR CLEANER BOX	0.00	0.00	one- *250.00 F
57	1		*AIR CLEANER HOSE	0.00	0.00	dis- *85.00 F
58	1		*AIR CON BLOWER	0.00	0.00	? *1,250.00 F
59	1		*HEATER UNIT	0.00	0.00	? *890.00 F
60	1		*FIRE WALL	0.00	0.00	? *2,000.00 F
61	1		*AIR CON CONDENSER	0.00	0.00	? *480.00 F
62	1		*AIR CON FAN BLADE	0.00	0.00	? *70.00 F
63	1		*AIR CON FAN MOTOR	0.00	0.00	? *360.00 F
64	1		*RADIATOR	0.00	0.00	? *580.00 F
65	1		*RADIATOR TOP HOSE	0.00	0.00	? *50.00 F
66	1		*RADIATOR FAN COWLING	0.00	0.00	? *120.00 F
67	1		*RADIATOR FAN COWLING ROUND	0.00	0.00	? *125.00 F
68	1		*RADIATOR FAN BLADE	0.00	0.00	? *55.00 F
69	1		*RADIATOR FAN MOTOR	0.00	0.00	? *360.00 F

F=Franchise part.

Sub Total (S\$)	15,943.00
+ Margin on L,N Items 10.00% (S\$)	1,594.30
Total Parts (S\$)	17,537.30

Kan Fook Sing Motor Workshop/GBJ4634T/31/05/2023 10:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	ERP STICKER	we- 20.00
2	1	FRONT NUMBER PLATE	bt- 50.00
3	1	FRONT WINDSCREEN GUM	we- 50.00
Sub Total (S\$)			120.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	SPRAYPAINTING CHARGES	New 1200	1,800.00
Labour Items			
2	TO CHECK WIRING SYSTEM	New 30	50.00
3	TO CHECK ALIGNMENT	New *	120.00
4	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	New	120.00
5	TO REMOVE/REFIT DASHBOARD	New 200	240.00
6	TO REMOVE/REFIT AIR CON BLOWER SYSTEM AND REFILL AIR CON GAS	New ?	180.00
7	TO REMOVE/REFIT CIUSHION AND ETC	New 60	100.00

Kan Fook Sing Motor Workshop/GBJ4634T/31/05/2023 10:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

No	Particulars	Lab.Type	Amount
8	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	1400 2,200.00
Gross Labour Cost (S\$)			4,810.00

Kan Fook Sing Motor Workshop/GBJ4634T/31/05/2023 10:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >