



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 5661K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT NUMBER PLATE GARNISH	NOT NECESSARY	65.80	-
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,389.20	-
1	FRONT BUMPER LOGO	NECESSARY	62.10	62.10
1	FRONT GRILLE	CUT	683.70	683.70
1	FRONT GRILLE LOGO	NECESSARY	160.50	160.50
2	HEADLAMP @\$1,769.90	O/S CUT	3,539.80	1,769.90
	LESS 10% DISCOUNT		-590.11	-267.62
			5,310.99	2,408.58
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	CRACKED	30.00	30.00
1	FRONT NUMBER PLATE HOLDER (SN)	NOT NECESSARY	30.00	-
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
			110.00	80.00
	<u>LABOUR</u>			
	PANEL BEATING, REMOVE AND REFIT PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		400.00	350.00
	SPRAY PAINTING TO AFFECTED AREA.		700.00	600.00
	WIRING CHECK.		50.00	30.00
	TO REMOVE FRONT BUMPER SENSOR.	NOT NECESSARY	100.00	-
	TO APPLY TUFF COAT.		150.00	30.00
			1,400.00	1,010.00
GRAND TOTAL			6,820.99	3,498.58
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,800.00

Report Ref No. CS/LPC23005552/Any3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.