

ASS. REC. BY: TauyhtREF: 05/LIP 3605565/T9Y3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP ☒ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$775 K. X

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seem _____ Consistent? : Yes or No

Est. Repairs _____ days Res.: Yes or No

Lump Sum _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNDS747 J Yr Regn: 2022, Jan.Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Mercedes Benz G63 AMG 3982Colour: Black A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: 24412 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: WIN4632762X405760Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModl: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

Rear

R/Bal. 6 mmL/Bal. 6 mm

D.O.I. _____

Survey held at Xin yunDes. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

\$ + RS \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Rep. Format: _____

Lump Sum / L.B. k: _____



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SND5747J MERCEDES GLE63 AMG 2022 Latest Model

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper	\$ 3,650.00 <i>de</i>
2	1	Bumper side bracket left	\$ 285.00 <i>x</i>
3	1	Bumper side bracket right	\$ 285.00 <i>x</i>
4	2	Bumper side reflector	\$ 400.00 <i>x</i>
5	1	Lower lip	\$ 690.00 <i>th</i>
6	1	GLE63 sport rim	\$ 4,500.00 <i>x</i>
7	1	Spare wheel plate	\$ 1,975.00 <i>x Ry</i>
8	1	Spare wheel plate logo	\$ 450.00 <i>ke</i>
9	1	Spare wheel round cover with seals & lock	\$ 4,485.00 <i>bt</i>
10	1	Rear end panel	\$ 5,500.00 <i>x</i>
11	2	Rear bumper 2 mounting at both side	\$ 800.00 <i>x</i>
12	2	Rear bumper lower number plate light holder-on bumper	\$ 500.00 <i>x</i>
13	2	Rear bumper number plate light -on bumper	\$ 700.00 <i>x</i>
14	4	Sensor bracket	\$ 1,000.00 <i>?</i>
15	2	Sensor	\$ 800.00 <i>?</i>
16	2	Accident blind spot radar sensor	\$ 2,400.00 <i>?</i>
17	1	Cable harness	\$ 650.00 <i>x</i>
Parts sub-total			\$ 29,070.00



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SND5747J MERCEDES GLE63 AMG 2022 Latest Model

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	12	Bumper clips	\$ 120.00 <i>3 Due</i>
2	10	Lower lip clips	\$ 100.00 <i>2 one</i>
3	10	Rear end panel clips	\$ 100.00 <i>x</i>
4	8	Spare wheel area clips	\$ 80.00 <i>x</i>
5	10	Number plate with cashing	\$ 120.00 <i>x</i>
6	20	Accident cable harness clips	\$ 200.00 <i>x</i>
<u>Special Nett Items</u>			\$ 720.00



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SND5747J MERCEDES GLE63 AMG 2022 Latest Model

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area	\$ 2,500.00 4000 500
2	To putty and spray painting affected area, including, behind bumper, RL fender, RL door, skirt and lower lip area	\$ 2,500.00 600
3	To check wiring and focus taillight	\$ 100.00 40
4	To apply anti rust proofing to front affected area.	\$ 300.00 X
5	To remove and install undercarriage parts to facilitate this repair	\$ 150.00 X
6	To balance the wheel-necessary	\$ 150.00 X
7	To conduct check spare wheel -necessary, check alignment & shape	\$ 200.00 X
8	To remove and install rear bumper sensor.	\$ 150.00 40
9	To conduct water test, after the repair	\$ 150.00 X
10	Polishing the affected area, after paint work, ceramic coating	\$ 1,200.00 X
11	To do brake calibration and top up brake oil	\$ 120.00 X
12	To remove bumper all internal trims and shift to new bumper	\$ 150.00 X
14	Programing and coding, remove accident fault code all	\$ 500.00 150
15	Remove and install rear spare wheel cover, tyre to facilitate repair	\$ 350.00 X
16	Remove and install rear blind spot module to facilitate repair	\$ 150.00 X
Total labour :		\$ 8,670.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufhin 97495749

19/6/23 @

C/S Resurvey after repair

3-4 days

Taufhin @ lkkauto.com