



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 4386D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BODY PANEL	TO REPAIR SEE LABOUR	1,875.50	-
1	TAILLAMP	NOT NECESSARY	379.60	-
1	SLIDING DOOR	TO REPAIR SEE LABOUR	1,611.90	-
1	FRONT DOOR WING MIRROR	DAMAGED	450.60	450.60
	LESS 25% DISCOUNT		-1,079.40	-112.65
			3,238.20	337.95
<u>SPECIAL NETT ITEMS</u>				
1	REAR BODY PANEL SEALANT (SN)	NOT NECESSARY	60.00	-
1	FRONT DOOR COMPANY ADDRESS STICKER (SN)	NECESSARY	30.00	30.00
			90.00	30.00
<u>LABOUR</u>				
	PANEL BEATING, REMOVE AND REFIT PARTS. INCLUSIVE OF THE REPAIR OF REAR BODY PANEL AND SLIDING DOOR.		1,000.00	200.00
	SPRAY PAINTING TO AFFECTED AREA.		1,000.00	600.00
	WIRING CHECK.		50.00	30.00
	TO APPLY TUFF COAT.		150.00	60.00
	TO TRANSFER SLIDING DOOR FITTINGS.	NOT NECESSARY	150.00	-
			2,350.00	890.00
GRAND TOTAL			5,678.20	1,257.95
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,000.00

Report Ref No. CS/LPC23005569/Aqy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.