

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23005575/UQP3M4**Date:** 14/06/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00006572302		
Claimant Vehicle No :	SDV6676Y	Insured Vehicle No :	XD8543S		
Date of Loss:	25/05/2023	Nature of Claim:	TP	Claim No:	SNM23D203761/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDV6676Y		
Make & Model:	NISSAN SYLPHY, 1.6 CVT ABS D/AIRBAG 2WD 4DR (A)	Engine No:	HR16957962B
Reg. Date:	25/03/2015 (Man. Year: 2014)	Chassis No:	MNTBBAB17Z0022548
Colour:	Black	Odometer:	79554 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,906.00	8,016.24	2,889.76	26.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,522.00	5,162.00	1,360.00	20.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	17,428.00	13,178.24	4,249.76	24.38

INSPECTION

Date of Assignment:	05/06/2023		
Date Inspected:	01/06/2023	Inspected At:	Autolution Industrial Pte Ltd (Ubi) 19 Ubi Road 4 Singapore 408623
Estimated Period of Repair:	0.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

SPECIAL REMARKS

MARKET VALUE : \$28,000.00 (est)

LTA REBATE : \$17,458.00

NETT VALUE : \$10,542.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jun 2023)
Parts:	143	NISSAN SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDV6676Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FLOOR PAN	Repair	826.10 FN	*- FN
2	1		*FENDER REAR LH	Badly Dented	1,717.70 FN	*1,717.70 FN
3	1		*EXTENSION REAR FENDER LH	* Check	279.60 FN	*- FN
4	1		*FENDER REAR RH	Badly Dented	1,717.70 FN	*1,717.70 FN
5	1		*EXTENSION-REAR FENDER RH	* Check	279.60 FN	*- FN
6	1		*PLATE-CLOSING,REAR RH	Twisted	39.50 FN	*39.50 FN
7	1		*PLATE-CLOSING,RR BUMPER LH	Twisted	35.40 FN	*35.40 FN
8	1		*REAR END PANEL	Badly Dented	475.90 FN	*475.90 FN
9	1		*FINISH REAR PARCEL SHELF	* Check	496.20 FN	*- FN
10	1		*HINGE TRUNK LID X2	Bent	91.20 FN	*91.20 FN
11	1		*TRUNK LID ASSY	Buckled	833.30 FN	*833.30 FN
12	1		*FINISHER ASSY - TRUNK LID OUTER	Cracked	199.40 FN	*199.40 FN
13	1		*LOCK ASSY-TRUNK	Twisted	78.90 FN	*78.90 FN
14	1		*CLIP TRUNK LID BAR	Necessary	6.00 FN	*6.00 FN
15	1		*BAR - TORSION, TRUNK LID RH	* Check	79.30 FN	*- FN
16	1		*BAR - TORSION, TRUNK LID LH	* Check	79.30 FN	*- FN
17	1		*ROD LOCK TRUNK LID	* Check	13.10 FN	*- FN
18	1		*BUMPER-RUBBER, TRUNK LID	* Check	10.80 FN	*- FN
19	1		*BMPR RUB-BACK DOOR DAMPER	* Check	15.80 FN	*- FN
20	1		*STRIKER-TRUNK LID LOCK	Twisted	70.80 FN	*70.80 FN
21	1		*SPACER	Bent	105.40 FN	*105.40 FN
22	1		*FINISHER LUGGAGE SIDE RH	Distorted	448.50 FN	*448.50 FN
23	1		*FINISHER - LUGGAGE SIDE LH	Distorted	448.50 FN	*448.50 FN
24	1		*CARPET-LUGGAGE FLOOR	Not Necessary	493.90 FN	*- FN
25	1		*SPACER - LUGGAGE FLOOR TRIM	Not Necessary	184.10 FN	*- FN
26	1		*PLATE LUGAGGE REAR	Bent	85.40 FN	*85.40 FN
27	1		*BRACKET REAR BUMPER LH	* Check	39.90 FN	*- FN
28	1		*BRACKET REAR BUMPER RH	* Check	39.90 FN	*- FN
29	1		*STAY RR BMPR LH	* Check	49.10 FN	*- FN
30	1		*STAY RR BMPR RH	* Check	52.10 FN	*- FN
31	1		*ENERGY ABSORBER REAR BUMPER LH	* Check	151.60 FN	*- FN
32	1		*ENERGY ABSORBER REAR BUMPER CENTER	* Check	40.50 FN	*- FN
33	1		*ENERGY ABSORBER - REAR BUMPER RH	* Check	101.10 FN	*- FN
34	1		*FASCIA - REAR BUMPER	Distorted	753.40 FN	*753.40 FN
35	1		*FINISH ASSY - TAILGATE INNER	Twisted	149.20 FN	*149.20 FN
36	1		*EMBLEM - NISSAN LOGO	Necessary	54.50 FN	*54.50 FN
37	1		*EMBLEM - SYLPHY WORD	Necessary	102.90 FN	*102.90 FN
38	1		*LAMP COMB RR,RH OUTER	Broken	422.70 FN	*422.70 FN
39	1		*LAMP COMB RR,LH OUTER	Broken	422.70 FN	*422.70 FN
40	1		*LAMP COMB RR,RH INNER	* Check	164.00 FN	*- FN
41	1		*LAMP COMB RR,LH INNER	Cracked	164.00 FN	*164.00 FN
42	1		*REFLEX REFLECTOR ASSY - REAR RH	Cracked	68.90 FN	*68.90 FN
43	1		*REFLEX REFLECTOR ASSY - REAR LH	Cracked	68.90 FN	*68.90 FN
44	1		*LICENSE PLATE LAMP ASSY X2	* Check	216.20 FN	*- FN
45	1		*QUARTER GLASS REAR RH	Necessary	553.80 FS	*553.80 FS
46	1		*GLASS-QUARTER REAR LH	Necessary	553.80 FS	*553.80 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR LICENCE PLATE	Bent	60.00 FS	*60.00 FS
F=Franchise part. S=SpcNett. N=NettItemDisc.						
Sub Total (S\$)					13,340.60	9,728.40
- Nett Item Discount on N Items 20.00/20.00% (S\$)					2,434.60	1,712.16
Total Parts (S\$)					10,906.00	8,016.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	New	240.00	240.00
2	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	New	110.00	110.00
3	APPLY SEALANT TO AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	New	500.00	100.00
4	INSTALL NUMBER PLATE & HOLDER (NPA)	New	0.00	0.00
5	REPAIR/REPLACE RR BUMPER, TAILGATE, END PANEL, FLOOR PAN, LH RR FENDER, RH RR FENDER & PANEL	New	2,520.00	2,240.00
6	RESPRAY ALL THE MENTIONED PANELS	New	2,000.00	1,500.00
7	CHECK ALL LIGHTING TEST AFTER REPAIRS	New	48.00	48.00
8	REMOVE & REFIX REAR BOOT GARNISH & TRIMS TO FACILITATE REPAIRS	New	114.00	114.00
9	TROUBLE SHOOT & FAULT FINDING USING NISSAN DIAGNOSTIC COMPUTER TO IDENTIFY FAULTS	New	120.00	0.00
10	REPLACE REVERSE CAMERA, FINISHER MOUNTING, ALIGNMENT SETTING & FUNCTION TEST	New	120.00	120.00
11	REMOVE/REFIX CARPET, SEATS TO FACILITATE REPAIRS	New	240.00	180.00
12	REMOVE & REINSTALL QUARTER GLASS REAR LH & RH	New	240.00	240.00
13	TO R&R REAR WINDSCREEN GLASS	New	150.00	150.00
14	TO R&R FUEL TANK	New	120.00	120.00
Gross Labour Cost (S\$)			6,522.00	5,162.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >