

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS / SMO 23005577 / unj 3

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLE293C

at Workshop m/s K & T

of \_\_\_\_\_

Insured: S L X 839 D

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Y	
N/S	O/S

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: \$ 82k.

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

644;

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: LIA # 53137

Veh No: SLE293C Yr Regn: 04/07/16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Land Rover Discovery Sport 1999

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 128035 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: SALCARAGOGH 613760

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/R m or

Tyre Size: F: 235/60R18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 6 mm

Rear R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 28/05/23

D.O.I. 5/6/23

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s rep.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 28/1/23

10/6/23 L/S @ 7000 inform AH Keary (Red. \$ 874.7. 56%)

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 3

1) \_\_\_\_\_

: Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

2) \_\_\_\_\_

Add Fee:  : Site Insp (\$ )

: Interview (\$ )

: Tech. Invs (\$ )

: Weekend (\$ )

Survey Fee:

Transportation:

\_\_\_\_ S + RS, \_\_\_\_ SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ \_\_\_\_\_ )

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	641I
Vehicle Details	
Vehicle No.:	SLE293C
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jun 2023
Vehicle Make:	LAND ROVER
Vehicle Model:	DISCOVERY SPORT 2.0 SI4 SE 7STR
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	015054165621204PT
Chassis No.:	SALCA2AG0GH613760
Maximum Power Output:	177.0 kW (237 bhp)
Open Market Value:	\$44,862.00
Original Registration Date:	04 Jul 2016
First Registration Date:	04 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$54,807.00 27403
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Jul 2026
PARF Rebate Amount:	\$35,624.00
Intended COE Rebate Details	
COE Expiry Date:	03 Jul 2026
COE Category:	B - Car above 1600cc or 971 W (130bhp)
COE Period(Years):	10
QP Paid:	\$57,010.00
COE Rebate Amount:	\$17,513.00
<b>Total Rebate Amount:</b>	<b>\$53,137.00</b>

The information contained herein is correct as at 07 Jun 2023

OK



**KT GARAGE PTE LTD** UEN: 201906115R  
 Auto Bay@ Kaki Bukit Entrance A  
 BLK 1 Kaki Bukit Ave 6 #01-04 Singapore 417883

*Not Allowed  
 4/5 #7000  
 3 days  
 5/6/23  
 Why the repair*

Date :

Total Pages :

TO: Whom it may concern

Our Customer : Balakrishnan Natalie

Vehicle No : **SLE293C**

Model : Land Rover Discovery

Manufacture Year :

Date of Accident : 28/5/2023

Total Estimate Repair Days :

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
<b>A.</b>	<b>Spare Parts</b>				
1	Front Bumper Face <i>3200</i>	1	\$4,844.00	\$4,844.00	Dis
2	Front Bumper Lower <i>1120</i>	1	\$3,383.00	\$3,383.00	Dis
3	LH Fog Lamp <i>650</i>	1	\$770.00	\$770.00	Cre
4	LH Fog Lamp Trim Top	1	\$40.00	\$40.00	Twi
5	LH Fog Lamp Trim Bottom	1	\$100.00	\$100.00	Twin
6	LH Fog Lamp Trim Outer Garnish	1	\$120.00	\$120.00	Cre
7	Front Bumper Top Bracket	1	\$341.25	\$341.25	Cre
8	Front Bumper Side Retainer	2	\$78.75	\$157.50	11 X
9	LH Fender Outer Garnish	1	\$323.75	\$323.75	M.S
10	LH Front Fender	1			R X
11	LH Wheel Bearing	1			11 X
12	Headlamp LH <i>2980</i>	1	\$3,237.50	\$3,237.50	scr/cre
	<b>Sub Total 1</b>			<b>\$13,317.00</b>	
<b>B.</b>	<b>Special Nett</b>				
1	LH Front Tyre	1	\$380.00	\$380.00	cut n/cx
	<b>Sub Total 2</b>			<b>\$380.00</b>	
<b>C</b>	<b>Labour</b>				
1	To panel beat, knock and straighten damaged panel and re-align the same			\$900.00	400
2	To transfer Tyre			\$50.00	11 X
3	To spray paint the affected areas			\$800.00	400
4	To rust proof all affected areas			\$80.00	11 X
5	To Conduct Wheel Alignment			\$120.00	11 X
6	To check all necessary lighting and wiring			\$100.00	20
	<b>Total Labour</b>			<b>\$2,050.00</b>	
	<b>Total Repair Cost</b>			<b>\$15,747.00</b>	
<b>* The above quoted are exclusive of GST.</b>					

LKK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Yours faithfully,  
 Kai f KT Garage Pte Ltd  
 Acknowledged by Repairer  
 Signature:  
 Date:

*APK*

Surveyor's Details	
Name	<i>Mera</i>
Contact	<i>9099662</i>
Survey Date	<i>5/6/23</i>
Recommender	Authorize / Not Authorize
Before Paint	Yes / No
Signature	<i>[Signature]</i>

*2-8875  
 102  
 79875  
 820  
 88072  
 202  
 7085*